

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/17/2024

Submitted Date:

12/17/2024

Document Number:

708905268**FIELD INSPECTION FORM**Loc ID 334999 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**42 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289103	WELL	PR	11/15/2007	GW	045-13672	FOSSIL CREEK RWF 533-6	PR
289104	WELL	PR	05/31/2009	GW	045-13671	FOSSIL CREEK RWF 33-6	PR
289105	WELL	PR	04/30/2009	GW	045-13670	FOSSIL CREEK RWF 433-6	PR
289106	WELL	PR	10/31/2008	GW	045-13669	FOSSIL CREEK RWF 333-6	PR
289107	WELL	PR	06/30/2009	GW	045-13668	FOSSIL CREEK RWF 542-6	PR
289108	WELL	PR	08/11/2009	GW	045-13667	FOSSIL CREEK RWF 543-6	PR
289109	WELL	PR	11/15/2007	GW	045-13666	FOSSIL CREEK RWF 334-6	PR
289110	WELL	PR	06/30/2009	GW	045-13665	FOSSIL CREEK RWF 444-6	PR
289111	WELL	PR	07/31/2009	GW	045-13664	FOSSIL CREEK RWF 344-6	PR
289112	WELL	PR	08/11/2009	GW	045-13663	FOSSIL CREEK RWF 44-6	PR
289113	WELL	PR	04/01/2012	GW	045-13662	FOSSIL CREEK RWF 534-6	PR
289114	WELL	PR	05/31/2009	GW	045-13661	FOSSIL CREEK RWF 434-6	PR
289115	WELL	PR	06/30/2009	GW	045-13660	FOSSIL CREEK RWF 544-6	PR
289116	WELL	PR	11/15/2007	GW	045-13659	FOSSIL CREEK RWF 34-6	PR
289117	WELL	PR	06/30/2009	GW	045-13658	FOSSIL CREEK RWF 532-6	PR

289118	WELL	PR	08/11/2009	GW	045-13657	FOSSIL CREEK RWF 443-6	PR
289119	WELL	PR	07/31/2009	GW	045-13656	FOSSIL CREEK RWF 343-6	PR
289120	WELL	PR	06/30/2009	GW	045-13655	FOSSIL CREEK RWF 43-6	PR

**General Comment:**

CECMC Inspection Report Summary  
On 12/17/2024 at approximately 13:04 hours, I, Compliance Specialist, Wayne Smelser  
Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 33-6 Pad.  
Location # 334999 in Garfield County Colorado.  
Location is within High Priority/Density/Black Bear Habitat areas.  
While there, I observed normal production operations.

This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tanks & Cataflow - hog panels		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Deadman # & Marked	# 1		
Comment:	Marked		
Corrective Action:		Date:	
Type: Bradenhead	# 18		
Comment:	RWF 43-6 well has a Taylor plug located on bradenhead, bradenhead valve is accessible.  Remaining 17 wells have no form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 18		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Gas Meter Run	# 18		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Cataflow		
Corrective Action:		Date:	
Type: Plunger Lift	# 18		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	STEEL AST		,	
Comment:	Tank equipped with telemetry					

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Centralized containment			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	289103	Type:	WELL	API Number: 045-13672	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	289104	Type:	WELL	API Number: 045-13671	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	289105	Type:	WELL	API Number: 045-13670	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	289106	Type:	WELL	API Number: 045-13669	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	289107	Type:	WELL	API Number: 045-13668	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	289108	Type:	WELL	API Number: 045-13667	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	289109	Type:	WELL	API Number: 045-13666	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	289110	Type:	WELL	API Number: 045-13665	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						

<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	289111	Type:	WELL	API Number: 045-13664 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	289112	Type:	WELL	API Number: 045-13663 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	289113	Type:	WELL	API Number: 045-13662 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	289114	Type:	WELL	API Number: 045-13661 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	289115	Type:	WELL	API Number: 045-13660 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	289116	Type:	WELL	API Number: 045-13659 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	289117	Type:	WELL	API Number: 045-13658 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			

Corrective Action:		Date:							
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	289118	Type:	WELL	API Number:	045-13657	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	289119	Type:	WELL	API Number:	045-13656	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	289120	Type:	WELL	API Number:	045-13655	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									



Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Small amount of light compaction
		Culverts				
Gravel						Sparse to none in some areas
		Ditches				
				Material Handling And Spill Prevention		Chemical tank containments
		Gravel				Sparse to none in sections
		Compaction				Light compaction in sections

Comment: Limited Stormwater inspection due to snow

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708905269	Inspection 708905268 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6829733">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6829733</a>
708905270	Inspection 708905268 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6829734">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6829734</a>