

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2024

Submitted Date:

12/10/2024

Document Number:

717000183**FIELD INSPECTION FORM**Loc ID 319893 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|---|---------------------------------|
| Supervisor, ECME | | jason.gomez@state.co.us | |
| , | | conor.pesicka@state.co.us | |
| , | | randy.silver@state.co.us | |
| , PDC | | rbucogccinspectionreports@c hevron.onmicrosoft.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------------|-------------|
| 201798 | WELL | TA | 03/30/2020 | GW | 001-07202 | CHAMPLIN 67 AMOCO F UNIT 1 | TA |

General Comment:[Follow-up inspection DOC #717000127](#)

| | | | |
|--|--|--------|------------------|
| Location | | | |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Emergency Contact Number: | | | |
| Comment: Adequate | | Date: | |
| Corrective Action: | | | |
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | It appears that no steps have been taken to correct sight. doc#717000127 Rule 606: Weeds, dead weeds. Within the designated setback (25 feet around any and all equipment), remove all debris and weeds per Rule 606. Corrective Action Date 12/27/2024 days. See attached photo | | |
| Corrective Action: | Remove all weeds around well head per Rule 606 | | Date: 12/27/2024 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Equipment: | | | |
| Type: Plunger Lift | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 201798 Type: WELL API Number: 001-07202 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 04/23/2024

Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 30

Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Appears to be plumbed to the surface

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|---|----------|------------|
| <p>CECMC Inspection Report Summary</p> <p>THIS IS A FOLLOW-UP INSPECTION FROM 11/1/2024 DOC #717000127 - NO CORRECTIONS APPEAR TO BE ADDERESD.</p> <p>On Friday December 4th at approximately 12:02pm. I, Inspector Chane Finkenbinder, conducted an on-site inspection.</p> <p>Operator: PDC / Chevron</p> <p>Location name: CHAMPLIN 67 AMOCO F UNIT #1</p> <p>API # 05-001-07202</p> <p>Location ID #: 319893</p> <p>County: Adams</p> <p>While there, I observed a TA well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Rule 606: Weeds, dead weeds. Within the designated setback (25 feet around any and all equipment), remove all debris and weeds around well head, per Rule 606. Corrective Action Date 12/27/2024 days. See attached photo # 1.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection report.</p> | finkenbc | 12/10/2024 |

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------------|---|
| 404025102 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6821454 |
| 717000184 | Follow-up inspection photo | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6821444 |