

Catamount Energy Partners
Cox 2
Inspection 708700072 Remedial Report

Comment: [Hole in stormwater berm on east side of well pad. See attached photos.](#)

Corrective Action: [Repair hole in stormwater berm](#)

Action Taken: Repaired hole in stormwater berm

Action Taken Date: 12/12/2024

