

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/11/2024

Submitted Date:

12/18/2024

Document Number:

713400550

FIELD INSPECTION FORM

Loc ID 312615 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---------------------------------------|---------|
| , LARAMIE | | cogccnotifications@laramie-energy.com | |
| Toews, Wesley | | wtoews@blm.gov | |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 222043 | WELL | PR | 03/01/2018 | GW | 077-08645 | HORSESHOE CANYON 2-20 | PR |

General Comment:[CECMC Inspection Report Summary](#)

On 12/11/2024 at approximately 12:04 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection at LARAMIE ENERGY LLC Horseshoe Canyon/2-20 Pad at Location ID #312615 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1. Equipment - Gas meter building roof paneling is damaged also open hole on metal siding/wildlife hazard available for entry by wildlife with a CA date of 12/25/2024

2. Equipment - Open access to wildlife on separators/wildlife hazard available for entry by wildlife with a CA date of 12/25/2024

3. Equipment - PRV vent line does not comply with CECMC pressure safety device rules with a CA date of 12/25/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

| Location | | | | |
|--|--|--------|--|-----------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | Access | | | |
| Corrective Action | | | | Date: |
| Overall Good: <input type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | OTHER | | | |
| Comment: | Sign near entrance to location is weathered & cracked but still legible | | | |
| Corrective Action: | | | | Date: |
| Type | TANK LABELS/PLACARDS | | | |
| Comment: | Produced water label is starting to peel and becoming illegible | | | |
| Corrective Action: | | | | Date: |
| Type | OTHER | | | |
| Comment: | Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank. | | | |
| Corrective Action: | | | | Date: |
| Type | BATTERY | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type | WELLHEAD | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | 1-800-891-6191/911 | | | |
| Corrective Action: | | | | Date: _____ |
| Overall Good: <input type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No _____ | | | | |
| Comment: _____ | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | WELLHEAD | | | |
| Comment: | Pipe rail fencing | | | |
| Corrective Action: | | | | Date: |
| Equipment: | | | | |
| | | | | corrective date |
| Type: Other | # 1 | | | |
| Comment: | PRV vent line does not comply with CECMC pressure safety device rules, refer to photos | | | |

| | | | | |
|-----------------------------------|---|--|-------|------------|
| Corrective Action: | Comply with CECMC pressure safety device rules | | Date: | 12/25/2024 |
| Type: Other | # 1 | | | |
| Comment: | Open access to wildlife on separators/wildlife hazard available for entry by wildlife, refer to photos | | | |
| Corrective Action: | Comply with CECMC wildlife rules | | Date: | 12/25/2024 |
| Type: Other | # 1 | | | |
| Comment: | Gas meter building roof paneling is damaged also open hole on metal siding/wildlife hazard available for entry by wildlife, refer to photos | | | |
| Corrective Action: | Comply with CECMC wildlife rules | | Date: | 12/25/2024 |
| Type: Bird Protectors | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Ancillary equipment | # 1 | | | |
| Comment: | Flameless gas infrared catalytic heater | | | |
| Corrective Action: | | | Date: | |
| Type: Vertical Separator | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Deadman # & Marked | # 6 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Bradenhead | # 1 | | | |
| Comment: | No form of pressure monitoring equipment. Bradenhead valve is accessible | | | |
| Corrective Action: | | | Date: | |
| Type: Gas Meter Run | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Plunger Lift | # 1 | | | |
| Comment: | Well on plunger lift | | | |
| Corrective Action: | | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|----------------------------------|----------|-----------|---------|--------|
| PRODUCED WATER | 1 | 100 BBLS | STEEL AST | | , |
| Comment: | Tank not equipped with telemetry | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|-----------------|------------|
| Condition | Inadequate |
| Other (Content) | |

| | |
|------------------|--|
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficent | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 222043 | Type: | WELL | API Number: | 077-08645 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | | | | | | |
| | | Ditches | | | | |
| | | Berms | | | | |
| | | Compaction | | | | |
| Berms | | | | | | |

Comment: Limited storm water inspection due to snow cover

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|---|----------|------------|
| Please refer to Equipment for corrective actions and Signs/Marker for comments. | popejoyd | 12/18/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 713400551 | Inspection Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6831256 |