

**Antler Energy LLC  
Amoco-Federal 21-1  
Location ID: 312970**



**When replaced additional information is required**



**Soil staining**

**Antler Energy LLC  
Amoco-Federal 21-1  
Location ID: 312970**




**Oily waste and debris**



**Oily waste and debris**

**Antler Energy LLC  
Amoco-Federal 21-1  
Location ID: 312970**



**Oily waste and debris**



**Debris**

**Antler Energy LLC  
Amoco-Federal 21-1  
Location ID: 312970**



**Unlabeled tank**



**No spill containment**

**Antler Energy LLC  
Amoco-Federal 21-1  
Location ID: 312970**



**Debris**




**Unlabeled debris**

Antler Energy LLC  
Amoco-Federal 21-1  
Location ID: 312970



Unlabeled debris



Missing required information

**Antler Energy LLC  
Amoco-Federal 21-1  
Location ID: 312970**



**Unregistered pit**



**Unregistered pit**

**Antler Energy LLC  
Amoco-Federal 21-1  
Location ID: 312970**



**Unregistered pit**



**Debris**

**Antler Energy LLC  
Amoco-Federal 21-1  
Location ID: 312970**



**Equipment out of service**



**Equipment out of service**

**Antler Energy LLC  
Amoco-Federal 21-1  
Location ID: 312970**



**Pit open to wildlife**



**Pit open to wildlife**

**Antler Energy LLC  
Amoco-Federal 21-1  
Location ID: 312970**



**Debris**



**Debris**

**Antler Energy LLC  
Amoco-Federal 21-1  
Location ID: 312970**



**Illegible label**



**Unlabeled production tank**

**Antler Energy LLC  
Amoco-Federal 21-1  
Location ID: 312970**



**No tank battery sign**



**Location from Northwest corner**

**Antler Energy LLC  
Amoco-Federal 21-1  
Location ID: 312970**



**Location from Southeast entrance**



**Location from Southeast entrance**