

Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938



Open end tank valves. Oily waste and staining




Debris.

Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938



Valve needs repaired




Valve needs repaired

Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938



Oily waste and staining



Debris

Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938



Missing required information



Hydrocarbon evidence on pit surface

**Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938**



Hydrocarbon evidence on pit surface



Hydrocarbon evidence on pit surface

**Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938**



Staining



Staining

**Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938**



Hydrocarbon evidence on pit surface



Open end load line

Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938



Load line



Open end load line

Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938



Stained soil



Staining

**Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938**



Debris. Unused equipment.



Open to wildlife

**Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938**



Missing bird protection



Location from Southwest corner



**Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938**



Location from Northwest corner



Location from Northeast corner

Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938



Open pit from Northwest corner



Open pit from Southwest corner