

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 34A-20-692 Pad

Location #: 335470



Photo # 3741 From entrance to location




Photo # 3742 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 34A-20-692 Pad

Location #: 335470



Photo # 3743 Location



Photo # 3744 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 34A-20-692 Pad

Location #: 335470



Photo # 3745 Location



Photo # 3746 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 34A-20-692 Pad

Location #: 335470



Photo # 3747 Location



Photo # 3748 Staining near separator

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 34A-20-692 Pad

Location #: 335470



Photo # 3749 Staining in secondary containment



Photo # 3750 Dead weeds/debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 34A-20-692 Pad

Location #: 335470



Dec 16, 2024 at 12:34:48 PM
CO



Dec 16, 2024 at 12:34:04 PM
CO

Photo # 3751 Dead weeds/debris

Photo # 3752 Dead weeds/debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 34A-20-692 Pad

Location #: 335470



Photo # 3753 Dead weeds/debris




Photo # 3754 Tank label weathered & some required info is illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 34A-20-692 Pad

Location #: 335470



Photo # 3755 Tank label damaged & some required info is illegible



Photo # 3756 PRV vent line on tank burner does not comply with CECCM pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 34A-20-692 Pad

Location #: 335470



Photo # 3757 PRV vent line on tank burner does not comply with CECMC pressure safety device rules



Photo # 3758 PRV vent line on tank burner does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 34A-20-692 Pad

Location #: 335470



Photo # 3759 SPECIALTY 44D wellhead sign weathered & becoming illegible



Photo # 3760 SPECIALTY 33C wellhead sign weathered & becoming illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 34A-20-692 Pad

Location #: 335470



Photo # 3761 SPECIALTY 33A wellhead sign weathered & becoming illegible