

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/11/2024

Submitted Date:

12/12/2024

Document Number:

710100336

FIELD INSPECTION FORM

Loc ID: 333171 Inspector Name: Anderson, Laurel On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Robinson, Taylor		taylor.robinson@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
Ahmadian, Alexander		alexander.ahmadian@state.co.us	
		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241909	WELL	PR	10/01/2023	OW	123-09700	MOSER 1-A	PR
481067	SPILL OR RELEASE	CL	07/12/2022		-	Moser 1A	EI

General Comment:

ECMC Environmental Inspection to determine progress on Moser 1A (Spill ID 481067/ Remediation 23510/Well API 123-09700). Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Incident information:

Spill Discovery Date: 11/8/2021
Days since spill discovery: 1,129 days (as of 12/11/2024)
Last report: 11/14/2022 (DENIED)

Current site status:

- No open excavation or monitoring wells
- Leaking hammer unions on piping at wellhead
- Wellhead producing- Pumpjack running during inspection
- Pumpjack engine exhaust staining ground
- Oil/grease leaking from pumpjack
- Soil stockpiled on location with no BMPs
- Salt/white staining on access road around pumpjack
- Weeds
- Debris

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

Hammer union leaking near wellhead. Pumpjack leaking oil. Pumpjack engine emitting black exhaust emissions. Soil staining from leaks/emissions. Trash/debris observed at soil stockpile.

Corrective Action:

Operator shall immediately control and contain spills/releases and investigate, clean up and document impacts per Rule 912.a.

Additionally, Operator shall conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).D.

Note: for any spills that do not meet the reporting requirements of Rule 912.b.; Operator shall provide documentation of the cleanup efforts (photo documentation and waste disposal manifests) to the Director per Rule 912.a.(5) - Operator may submit documentation via FIRR.

Operator shall properly handle, transport and dispose of E&P waste in accordance with 905 Series Rules. For non E&P waste Operator shall handle waste in accordance with Rule 906.

Date: 12/12/2024

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 241909 Type: WELL API Number: 123-09700 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 481067 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404026913	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6822961
710100337	Photo Documentation - Moser 1A	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6822953