

WELL NAME: SALIDA 44-26, API #: 071-07675, INSP. # 716300321



PHOTO 1: WELL SIGN



PHOTO 2: LOCATION.





PHOTO 3: WELLHEAD AND EQUIPMENT.





PHOTO 4: STORMWATER HAS ERODED OUT OF BMP DITCH AND HAS CAUSED CHENNELING DOWN AND ACROSS ROW IS MULTIPLE AREAS. **Install or repair required BMPs per Rule 1002.f.(2)C . CA DATE 12/26/2024.**

WGS84
±12ft

37.13833, -104.84891

ft
±10ft

7001

°M
±10

NW337



Colorado Oil & Gas Conservation commission
© 16-Dec-24 11:32:12

PHOTO 5: STORMWATER HAS ERODED OUT OF BMP DITCH AND HAS CAUSED CHENNELING DOWN AND ACROSS ROW IS MULTIPLE AREAS. Install or repair required BMPs per Rule 1002.f.(2)C . CA DATE 12/26/2024.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

WGS84 ±16ft 37.13832, -104.84892 Δ ft ±13ft 6996 °,M ±10 SE162



Colorado Oil & Gas Conservation commission
© 16-Dec-24 11:32:22

PHOTO 6: STORMWATER HAS ERODED OUT OF BMP DITCH AND HAS CAUSED CHENNELING DOWN AND ACROSS ROW IS MULTIPLE AREAS. *Install or repair required BMPs per Rule 1002.f.(2)C . CA DATE 12/26/2024.*