

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2024

Submitted Date:

12/04/2024

Document Number:

716300318**FIELD INSPECTION FORM**Loc ID 309360 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**ECMC Operator Number: 10758Name of Operator: OGRIS OPERATING LLCAddress: PO BOX 53467City: MIDLAND State: TX Zip: 79710**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|--------------|-------------------|---------------------------------|
| BACA, DAVE | 719-859-4066 | dbaca@ogrisop.com | All Inspections |
| B WARD, GIENA | | gward@ogrisop.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 293761 | WELL | PR | 11/28/2007 | CBM | 071-09441 | HILL RANCH EAST 23-10 | PR |

General Comment:

| | | | | | |
|--|------|---|--|-----------------|--|
| Location | | | | | |
| Overall Good: <input checked="" type="checkbox"/> | | | | | |
| Emergency Contact Number: | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: _____ | |
| Overall Good: <input checked="" type="checkbox"/> | | | | | |
| Spills: | | | | | |
| Type | Area | Volume | | | |
| In Containment: No | | | | | |
| Comment: | | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | | |
| Equipment: | | | | corrective date | |
| Type: Progressive Cavity | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Type: Vertical Separator | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Type: Gas Meter Run | # 1 | | | | |
| Comment: | | CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR. | | | |
| Corrective Action: | | | | Date: | |
| Type: Deadman # & Marked | # 4 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Type: Ancillary equipment | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Type: Bradenhead | # 1 | | | | |
| Comment: | | IS ACCESSABLE | | | |
| Corrective Action: | | | | Date: | |
| Venting: | | | | | |
| Yes/No | NO | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-------------------------|--------|----------------------------|------|------------------------|-----------|------------------|----|---------------|----|
| Facility ID: | 293761 | Type: | WELL | API Number: | 071-09441 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | PR | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: | | 05/06/2024 | | Annual Brhd Completed? | | Yes | | | |
| Last Brhd Test Results | | Initial Surf Csg Pressure: | | 0 | | Fluid Type: NONE | | | |
| | | End Surf Csg Pressure: | | 0 | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| | | | | | | |

Comment:
Corrective Action: Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

| | | | | |
|-----------------------------|------------------|-----------------------|-----------------------|--------------------------|
| Type: <u>Produced Water</u> | Lined: <u>NO</u> | Pit ID: <u>298171</u> | Lat: <u>37.067200</u> | Long: <u>-104.856200</u> |
|-----------------------------|------------------|-----------------------|-----------------------|--------------------------|

Reference Point: Other: Length: Width:

Lining:

Liner Type: Liner Condition:
Comment:
Corrective Action: Date:

Fencing:

Fencing Type: None Fencing Condition:
Comment:
Corrective Action: Date:

Netting:

Netting Type: Netting Condition:
Comment:
Corrective Action: Date:

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES
Comment:
Corrective Action: Date:

ECMC Comments

| Comment | User | Date |
|---|----------|------------|
| THIS IS A FOLLOW UP TO INSP. DOC. #695108656, CA'S HAVE BEEN ADDRESSED. | beardslt | 12/04/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------|---|
| 716300319 | INSP. PHOTOS | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834078 |