

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/13/2024

Submitted Date:

12/19/2024

Document Number:

700300768**FIELD INSPECTION FORM**Loc ID 325310 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 31250Name of Operator: FRITZ & DIGMAN INCAddress: PO BOX 70024City: ALBUQUERQUE State: NM Zip: 87197-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kosola, Jason		jason.kosola@state.co.us	
Flores, Marie		marie@walsheng.net	contractor for various operators in SW
Digman, Rebecca	505-379-8689	rcdigman@yahoo.com	
Digman, Bernie	575-640-1867	berniekdigman@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214538	WELL	SI	06/01/2023	OW	067-06141	DAKOTA FEE 1	WK

General Comment:

Conduct spill response from previous days release. RIH with packerto 260', pressure to 460 psi, no leak on 4 1/2", RIH to 1260', no leak on 4 1/2". Only circulation is through perms shot on 12/12 at 1298'.

Extent of spill area demonstrates secondary containment of fluids COA on Form 6 was not achived.

Plugging operations continued with cracked casing flange leaking fluid and vacuum truck used to remove from cellar while circulating.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	400 bbl rental tank not marked or contents labeled		
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	WELLHEAD	>= 5 bbls		
Comment:	While trying to establish circulation after perforating tubing at 1298' oil and produced water came to surface around wellhead through a cracked casing flange. Rig supervisor there was also a hose that came loose and contributed to the spill at wellhead and towards rig and equipment to the south. Vacuum truck and crews were responding to spill and removing free fluids when ECMC staff arrived. Operator filed Form 19 but has not submitted a Form 27 as required			
Corrective Action:	Submit Form 27 related to spill and clean-up/remediation. (Note: a Form 27 is also required for P&A)			Date: 01/15/2025

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 214538 Type: WELL API Number: 067-06141 Status: SI Insp. Status: WK**Cement**Cement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): CR @ 1298'Cement Volume (sx): 147

Good Return During Job: _____

Cement Type: g

Comment: Stage tubing 4 1/2" and packer tubing in 7" casing, periodically pressuring up to test for casing leaks. Determine flow from previous day was circulation through perfs @ 1359'. Run tubing back in with cement retainer @ 1298', pump 30 bbls water to clean up, pump 147 sacks total through retainer. Shut down for weekend.

Corrective Action: _____

Date: _____

WorkoverComment: Drake Well service rig and cementing equipment

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700300772	spill and response	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834543
700300773	vac truck cleaning up free fluids	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834544
700300774	spill area	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834546