

FORM  
INSPRev  
X/20

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/10/2024

Submitted Date:

12/19/2024

Document Number:

715201314

### FIELD INSPECTION FORM

Loc ID 415505 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10722  
Name of Operator: KTM OPERATING LLC  
Address: 2851 JOHNSTON ST PMB 550  
City: LAFAYETTE State: LA Zip: 70503

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Hecht, Jaime	832-531-1711	jaime.hecht@dynacloud.io	
Vincent, Kenny	(337) 654-9404	kvincent@reagan.com	Principal Agent

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415730	WELL	TA	07/17/2023	OW	073-06404	CRAIG 6-4	TA

**General Comment:**

SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt road through pasture		
Corrective ActionL		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	No lease sign at wellhead		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	01/17/2025

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:	Deadmen need marked		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Solar powered cathodic rectifier and gas scrubber		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	DPEG 320		
Corrective Action:		Date:	
Type: Prime Mover	# 0		
Comment:	Removed from unit at time of inspection		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 415730 Type: WELL API Number: 073-06404 Status: TA Insp. Status: TA

**Producing Well**

Comment: Central tank battery 1625' WNW at Craig 4-4

Corrective Action:

Date:

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well is TA at time of inspection. Passing MIT performed on 4/13/20. Subsequent passing MIT will be due on 4/13/25

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Compaction	Pass			

Comment: [Location is grassed over](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715201395	location photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834946">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834946</a>