

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/10/2024

Submitted Date:

12/19/2024

Document Number:

715201315

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
309615 _____ Welsh, Brian _____ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10722
Name of Operator: KTM OPERATING LLC
Address: 2851 JOHNSTON ST PMB 550
City: LAFAYETTE State: LA Zip: 70503

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Vincent, Kenny	(337) 654-9404	kvincent@reagan.com	Principal Agent
Hecht, Jaime	832-531-1711	jaime.hecht@dynacloud.io	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294992	WELL	TA	08/03/2022	OW	073-06316	CRAIG 15-34	TA

General Comment:

[SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location](#)

Location				
Lease Road:				
	Type	Access		
	comment:	Dirt road through pasture		
	Corrective Action		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
	Type	WELLHEAD		
	Comment:	No lease sign at wellhead		
	Corrective Action:	Install sign to comply with Rule 605.d.	Date: 01/17/2025	
Emergency Contact Number:				
	Comment:	<input style="width: 100%;" type="text"/>		
	Corrective Action:	<input style="width: 100%;" type="text"/>		
Date: _____				
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
	Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
	Type	WELLHEAD		
	Comment:	Metal panels around wellhead		
	Corrective Action:		Date:	
Venting:				
	Yes/No			
	Comment:			
	Corrective Action:		Date:	
Flaring:				
	Type			
	Comment:			
	Corrective Action:		Date:	

Inspected Facilities

Facility ID: 294992 Type: WELL API Number: 073-06316 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is TA at time of inspection. Passing MIT performed on 4/13/20. Subsequent passing MIT will be due on 4/13/25

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715201394	wellhead photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834947