

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/16/2024

Submitted Date:

12/20/2024

Document Number:

713400558

## FIELD INSPECTION FORM

 Loc ID 335550 Inspector Name: Popejoy, Dusty On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

34 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**
 ECMC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: 1058 COUNTY ROAD 215  
 City: PARACHUTE State: CO Zip: 81635
**Contact Information:**

Contact Name	Phone	Email	Comment
Smelser, Wayne		wayne.smelser@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293098	WELL	PR	12/14/2012	GW	045-14882	DIXON A8	PR
293100	WELL	PR	10/15/2012	GW	045-14884	DIXON A3	PR
293101	WELL	PR	09/13/2012	GW	045-14885	DIXON A2	PR
293102	WELL	PR	12/14/2012	GW	045-14886	DIXON A1	PR
293104	WELL	PR	12/14/2012	GW	045-14888	DIXON A5	PR
293105	WELL	PR	12/14/2012	GW	045-14889	DIXON A6	PR
293106	WELL	PR	09/12/2012	GW	045-14890	DIXON A9	PR
293157	WELL	PR	12/14/2012	GW	045-14905	DIXON A11	PR

**General Comment:**[CECMC Inspection Report Summary](#)

On 12/16/2024 at approximately 11:45 hours, Compliance Inspector Dusty Popejoy conducted a Follow up inspection at TEP ROCKY MOUNTAIN LLC DIXON A Pad at Location ID #335550 in Garfield County, Colorado.

Please refer to inspection 708904236 conducted on 07/25/2024, previous corrective actions have been completed.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Normal production operations were observed.

Location				
<b>Lease Road:</b>				
	Type	Access		
	comment:	Access		
	Corrective Action:			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
	Type	OTHER		
	Comment:	Sign at entrance to location		
	Corrective Action:			Date:
	Type	BATTERY		
	Comment:			
	Corrective Action:			Date:
	Type	CONTAINERS		
	Comment:	Chemical tank		
	Corrective Action:			Date:
	Type	WELLHEAD		
	Comment:			
	Corrective Action:			Date:
	Type	OTHER		
	Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
	Corrective Action:			Date:
	Type	TANK LABELS/PLACARDS		
	Comment:	1 production tank label is showing signs of disrepair and becoming illegible, all other production tank labels are showing signs of disrepair, refer to photos		
	Corrective Action:			Date:
Emergency Contact Number:				
	Comment:	970-285-9377/911		
	Corrective Action:			Date: _____
<b>Good Housekeeping:</b>				
	Type	DEBRIS		
	Comment:	Light debris, refer to photos		
	Corrective Action:			Date:
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	<a href="#">Livestock panels</a>		
Corrective Action:			Date:
Type	LOCATION		
Comment:	<a href="#">Farm fence/Barbed wire</a>		
Corrective Action:			Date:
Type	OTHER		
Comment:	<a href="#">Pig station - pipe rail fence</a>		
Corrective Action:			Date:
Type	OTHER		
Comment:	<a href="#">Chemical tank - Livestock panels</a>		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 8		
Comment:	<a href="#">All wells on plunger lift</a>		
Corrective Action:			Date:
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	<a href="#">Chemical tank</a>		
Corrective Action:			Date:
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 8		
Comment:	<a href="#">All Bradenhead valves are accessible with telemetry for monitoring, except for Dixon A5 bradenhead is not equipped with telemetry for monitoring but valve is accessible</a>		

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	HEATED STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:	Tank not equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:	Tank not equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment: Centralized containment				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	HEATED STEEL AST		,
Comment: Tank equipped with telemetry					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment: Centralized containment				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	293098	Type:	WELL	API Number:	045-14882	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	293100	Type:	WELL	API Number:	045-14884	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	293101	Type:	WELL	API Number:	045-14885	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	293102	Type:	WELL	API Number:	045-14886	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	293104	Type:	WELL	API Number:	045-14888	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	293105	Type:	WELL	API Number:	045-14889	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	293106	Type:	WELL	API Number:	045-14890	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	293157	Type:	WELL	API Number:	045-14905	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

**Producing Well**

Comment: Producing well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Silt Fences				
Compaction						
		Compaction				
				Material Handling And Spill Prevention		Chemical tank containment
Berms						
		Ditches				
		Culverts				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Signs/Marker &amp; Housekeeping for comments.</a>	popejoyd	12/19/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400559	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6835680">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6835680</a>