

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/20/2024

Submitted Date:

12/20/2024

Document Number:

717700963

FIELD INSPECTION FORM

Loc ID 460447 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
460450	WELL	PR	09/01/2024	OW	123-49385	State C24-730	PR
460452	WELL	SI	03/01/2024	LO	123-49387	State C24-717	SI
460455	WELL	PR	09/01/2024	OW	123-49390	State C24-745	PR
460456	WELL	PR	09/01/2024	OW	123-49391	State C24-725	PR

General Comment:

[This is a routine audit on the location](#)

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	No battery sign		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	Adequate
Corrective Action:	
	Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	#		
Comment:	Gas Lift Skid		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 460450 Type: WELL API Number: 123-49385 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/16/2024 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: NONE
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 460452 Type: WELL API Number: 123-49387 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment: SI
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 05/15/2024 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 460455 Type: WELL API Number: 123-49390 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/16/2024 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONE
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 460456 Type: WELL API Number: 123-49391 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:	Date:
BradenHead	
Date of Last Brhd Test: <u>10/16/2024</u>	Annual Brhd Completed? <u>Yes</u>
Last Brhd Test Results Initial Surf Csg Pressure: <u>12</u>	Fluid Type: <u>NONE</u>
End Surf Csg Pressure: <u>0</u>	
Comment: <input style="width: 90%;" type="text"/>	
Corrective Action: <input style="width: 90%;" type="text"/>	Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717700964	Annotation Report	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6836003
717700965	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6836004