

Inspection Photos

Loc: 485760

Operator: WAVETECH HELIUM INC

Inspection Date: 12/18/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south along the access road. The access road needs to be reduced in size by reclaiming and decompacting soils.



Inspection Photos



Photo 2. Facing south toward the wellsite..



Inspection Photos



Photo 3. North side of the location facing east. Topsoil is stored along the north side of the location and has not been stabilized or replaced for interim reclamation.



Inspection Photos



Photo 4. Facing toward the northeast side of the location. There is erosion along the topsoil pile which is mixing soil into the pad surface and subsoils. The topsoil is not stabilized or protected.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:485760 | Date: 12/18/2024

Inspection Photos



Photo 5. There is unused pipe at the wellhead that needs to be removed. There is no sign posted at the wellhead.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:485760 | Date: 12/18/2024

Inspection Photos



Photo 6. There is significant gully erosion along the fill slope which has washed sediment out into the adjacent crop field. Red arrow points to 4.5 ft. shovel.



Inspection Photos



Photo 7. Facing southwest toward the fill slope which has eroded and transported sediment offsite.



Inspection Photos



Photo 8. There is a bucket of oil, sign and tools at this south side of the location.



Inspection Photos



Photo 9. Southwest side of the location facing north. There is plastic trash that need to be removed.



Inspection Photos



Photo 10. There is a spill and stained soils at the southwest corner that must be cleaned up.

