

Construction and Stormwater Inspection

Date: 12/19/2024

Operator: CARBON STORAGE SOLUTIONS LLC -
10786

Location ID: 487295

Inspection Document #: 708201879

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Front Range 2
Location ID: 487295



Photo 1. Per Rule 406.c, a copy of the Form 2A was posted on location near the entrance. Note : The Form 2A had water damage, replacement advised.

Inspection Photos
Location Name: Front Range 2
Location ID: 487295



Photo 2. Stained soil observed on the eastern portion of the drilling pad.

Inspection Photos
Location Name: Front Range 2
Location ID: 487295



Photo 3. Continued from Photo 2; stained soil observed on the eastern portion of the drilling pad.

Inspection Photos
Location Name: Front Range 2
Location ID: 487295



Photo 4. Taken from the southern portion of the disturbance area. Topsoil stockpile and other portions of the disturbance area appear to have been stabilized with drill seeding and crimped straw observed.

Inspection Photos
Location Name: Front Range 2
Location ID: 487295



Photo 5. Trash/debris observed on the southern portion of the disturbance areas and off-location.



Photo 6. Ditch and berm with sediment trap observed on the east side of the topsoil stockpile.

Inspection Photos
Location Name: Front Range 2
Location ID: 487295



Photo 7. Southeast portion of the disturbance area. Portions of the perimeter berm have evidence of unconsolidated materials which might require additional maintenance to prevent erosion degradation and/or sediment transport.

Inspection Photos
Location Name: Front Range 2
Location ID: 487295



Photo 8. Continued from Photo 7; east side of disturbance area. Unconsolidated material and trash/debris observed.

Inspection Photos
Location Name: Front Range 2
Location ID: 487295



Photo 9. Ditch and berm with sediment trap observed on the east side of the topsoil stockpile.

Inspection Photos
Location Name: Front Range 2
Location ID: 487295



Photo 10. Northeast portion of the disturbance area. Portions of the perimeter berm have evidence of unconsolidated materials which might require additional maintenance to prevent erosion degradation and/or sediment transport.

Inspection Photos
Location Name: Front Range 2
Location ID: 487295



Photo 11. Northwest portion of the disturbance area. Perimeter stormwater control measures have been installed and disturbance areas appear to be stabilized with seeding and mulch.

Inspection Photos
Location Name: Front Range 2
Location ID: 487295



Photos 12 & 13. Southwest portion of the disturbance area. Perimeter stormwater control measures have been installed and disturbance areas appear to be stabilized with seeding and mulch.