

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2024

Submitted Date:

12/20/2024

Document Number:

698602701**FIELD INSPECTION FORM**Loc ID 337238 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284351	WELL	PR	04/19/2006	GW	125-09951	JOSH 21-4 4N46W	PR

**General Comment:**

Follow-up Inspection. Inspector is completing Follow-up inspection as required by FIRR. Follow-up inspection will ensure corrective actions taken by Operator adequately address and comply with rule requirements cited in 12/04/2024 FIR document number 698602698.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained County Road.		
Corrective ActionL		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well sign at wellhead location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency contact information posted on well sign.

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			
Produced Water	WELLHEAD	<= 1 bbl			
Comment:	CA - Active release at wellhead. Less than 1 barrel.				
	Corrective action completed.				
Corrective Action:				Date:	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	CA - Well had previous active release at wellhead from check valve. Repair work disconnected water leg from wellhead tree eliminating pressure at the check valve. Current leak is from broken gauge face used as a plug on riser plug at wellhead.		
	Corrective action completed.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	284351	Type:	WELL	API Number:	125-09951	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Rods and tubing in wellbore. Tubing valve not connected. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698602733	Inspection photos.	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6837099">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6837099</a>