

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 23A-21-692 Pad

Location #: 413900



Photo # 3840 From entrance to location




Photo # 3841 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 23A-21-692 Pad

Location #: 413900



Photo # 3842 Location



Photo # 3843 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 23A-21-692 Pad

Location #: 413900



Dec 16, 2024 at 1:22:52 PM
CO

Photo # 3844 Location



Dec 16, 2024 at 1:40:20 PM
CO

Photo # 3845 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 23A-21-692 Pad

Location #: 413900



Photo # 3846 Location



Photo # 3847 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 23A-21-692 Pad

Location #: 413900



Photo # 3848 Location



Photo # 3849 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 23A-21-692 Pad

Location #: 413900



Photo # 3850 Unused hoses in secondary containment



Photo # 3851 Unused hoses in secondary containment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 23A-21-692 Pad

Location #: 413900



Photo # 3852 Battery sign weathered & cracking/some info is illegible/sign does not comply with CECMC rules



Photo # 3853 Tank label lacks capacity

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 23A-21-692 Pad

Location #: 413900



Photo # 3854 Tank label weathered & some required info is illegible/does not comply with CECMC rules

Photo # 3855 Tank label weathered & some required info is illegible/does not comply with CECMC rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 23A-21-692 Pad

Location #: 413900



Photo # 3856 PRV vent line on tank burner does not comply with CECMC pressure safety device rules



Photo # 3857 PRV vent line on tank burner does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY 23A-21-692 Pad

Location #: 413900



Photo # 3858 PRV vent line on tank burner does not comply with CECMC pressure safety device rules



Photo # 3859 PRV vent line on tank burner does not comply with CECMC pressure safety device rules