

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC GUCCINI Pad

Location ID: 335083

Date: 12/16/2024



Photo # 1267 Entrance to location



Photo # 1268 Location

# Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC GUCCINI Pad

Location ID: 335083

Date: 12/16/2024



Photo # 1276 Location



Photo # 1281 Location

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC GUCCINI Pad

Location ID: 335083

Date: 12/16/2024



Photo # 1287 Location



Photo # 1288 Location

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC GUCCINI Pad

Location ID: 335083

Date: 12/16/2024



Photo # 1283 SW corner of location



Photo # 1302 NE corner of location

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC GUCCINI Pad

Location ID: 335083

Date: 12/16/2024



Photo # 1306 SE corner of location



Photo # 1311 NW corner of location

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC GUCCINI Pad

Location ID: 335083

Date: 12/16/2024



Photo # 1271 PRV vent line does not comply with CECMC pressure safety device rules

Photo # 1273 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos  
Location: TEP ROCKY MOUNTAIN LLC GUCCINI Pad  
Location ID: 335083  
Date: 12/16/2024



Photo # 1277 Debris



Photo # 1285 Debris

# Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC GUCCINI Pad

Location ID: 335083

Date: 12/16/2024



Photo # 1301 Debris



Photo # 1037 Debris