

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/16/2024

Submitted Date:

12/20/2024

Document Number:

713400567

FIELD INSPECTION FORM

 Loc ID 335083 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 ECMC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635
Findings:

- 27 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|-------|------------------------------------|---------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| Smelser, Wayne | | wayne.smelser@state.co.us | |
| , TEP | | COGCCInspectionReports@terraep.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 277912 | WELL | PR | 11/01/2014 | GW | 045-10809 | GUCCINI 41D-20-692 | PR |
| 277913 | WELL | PR | 06/07/2006 | GW | 045-10810 | GUCCINI 41B-20-692 | PR |
| 277914 | WELL | PR | 06/07/2006 | GW | 045-10811 | GUCCINI 31D-20-692 | PR |
| 277915 | WELL | PR | 06/05/2006 | GW | 045-10812 | GUCCINI 31B-20-692 | PR |
| 290198 | WELL | PR | 08/01/2024 | GW | 045-14053 | GUCCINI 31A-20-692 | PR |
| 290200 | WELL | PR | 04/17/2012 | GW | 045-14052 | GUCCINI 41C-20-692 | PR |
| 290202 | WELL | PR | 09/05/2007 | GW | 045-14051 | GUCCINI 31C-20-692 | PR |
| 290203 | WELL | PR | 09/05/2007 | GW | 045-14050 | GUCCINI 41A-20-692 | PR |

General Comment:[CECMC Inspection Report Summary](#)

On 12/16/2024 at approximately 16:22 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC GUCCINI Pad at Location ID #335083 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1. 2 PRV vent lines do not comply with CECMC pressure safety device rules with a CA date of 12/27/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Production tanks for wells are located on the CB-TG Land Pad, location #418555

| Location | | | |
|--|--|--------|-------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Access | | |
| Corrective ActionL | | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | OTHER | | |
| Comment: | Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks. | | |
| Corrective Action: | | | Date: |
| Type | CONTAINERS | | |
| Comment: | Chemical tanks | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | 970-285-9377/911 | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | Debris - refer to photos | | |
| Corrective Action: | | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | OTHER | | |
| Comment: | Pig station - pipe rail fence | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | Livestock panels | | |
| Corrective Action: | | | Date: |
| Type | SEPARATOR | | |
| Comment: | Hog panels | | |

| | | | |
|--------------------|-----------------------------------|-------|--|
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Chemical tanks - Livestock panels | | |
| Corrective Action: | | Date: | |

| Equipment: | | | corrective date |
|-----------------------------------|---|-------|-----------------|
| Type: Deadman # & Marked | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 3 | | |
| Comment: | Chemical tanks | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Other | # 2 | | |
| Comment: | PRV vent lines do not comply with CECMC pressure safety device rules, refer to photos | | |
| Corrective Action: | Comply with CECMC pressure safety device rules | Date: | 12/27/2024 |
| Type: Bradenhead | # 8 | | |
| Comment: | All Bradenhead valves are accessible - Guccini 31B bradenhead is equipped with telemetry for monitoring | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Liquid nitrogen tank | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 8 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 8 | | |
| Comment: | All wells on plunger lift | | |
| Corrective Action: | | Date: | |
| Type: Pig Station | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 8 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Venting: | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|--|--------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 277912 | Type: | WELL | API Number: | 045-10809 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 277913 | Type: | WELL | API Number: | 045-10810 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 277914 | Type: | WELL | API Number: | 045-10811 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 277915 | Type: | WELL | API Number: | 045-10812 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 290198 | Type: | WELL | API Number: | 045-14053 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 290200 | Type: | WELL | API Number: | 045-14052 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 290202 | Type: | WELL | API Number: | 045-14051 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290203 Type: WELL API Number: 045-14050 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|----------------------------|
| Compaction | | | | | | |
| Berms | | | | | | |
| | | Gravel | | | | Sparse |
| Ditches | | | | | | |
| Rip Rap | | | | | | |
| | | Rip Rap | | | | |
| | | | | Material Handling And Spill Prevention | | Chemical tank containments |
| | | Compaction | | | | |
| | | Ditches | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|--|----------|------------|
| Please refer to Equipment for corrective action and Housekeeping for comments. | popejoyd | 12/20/2024 |
| Production tanks for wells are located on the CB-TG Land Pad, location #418555 | | |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 713400568 | Inspection Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6837367 |