

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/19/2024

Submitted Date:

12/21/2024

Document Number:

708905300

FIELD INSPECTION FORM

Loc ID 335444 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

Findings:

- 19 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
QB Energy		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278812	WELL	PR	08/01/2023	GW	045-10941	GMU 23-8C (H23NW)	PR
278813	WELL	PR	08/01/2023	GW	045-10940	GMU 23-2C (H23NW)	PR

General Comment:

[CECMC Inspection Report Summary](#)
 On 12/19/2024 at approximately 16:14 hours, I, Compliance Specialist, Wayne Smelser
 Conducted an on-site inspection at QB Energy GMU 23-8C (H23NW) Pad.
 Location # 335444 in Garfield County Colorado.
 Location is within High Priority/Density/NSO/Black Bear Habitat areas.
 Location is within Rule 411a Surface Water Internal Buffer & Rule 411b Generalized External Buffer.
 Location is approximately 61 yards from Dry Creek.
 While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - PRV vent line on tank burner does not comply with CECMC pressure safety device rules with a CA date of 12/28/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Signs at separators		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-2615		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Pig station - pipe rail fence		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 2		corrective date
Comment:	Pressure transducers located on bradenheads, bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:	Marked		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	PRV vent line on tank burner does not comply with CECMC pressure safety device rules		
Corrective Action:	Comply with CECMC pressure safety device rules	Date:	12/28/2024
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	HEATED STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 278812 Type: WELL API Number: 045-10941 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 278813 Type: WELL API Number: 045-10940 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Tracking Pad				Aggregate/gravel based VTC
		Gravel				Sparse in most areas
Compaction						Small amount of light compaction
Gravel						Sparse to none in some areas
Berms						
		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Equipment for corrective action	smelserw	12/21/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708905301	Inspection 708905300 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6837714
708905302	Inspection 708905300 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6837715