

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/10/2024

Submitted Date:

12/15/2024

Document Number:

713400543

FIELD INSPECTION FORM

Loc ID 312624 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response RequestedANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, LARAMIE		cogccnotifications@laramie-energy.com	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222053	WELL	PR	09/01/2024	GW	077-08655	HORSESHOE CANYON 3-27	PR

General Comment:

CECMC Inspection Report Summary

On 12/10/2024 at approximately 15:16 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection at LARAMIE ENERGY LLC Horseshoe Canyon/3-27 Pad at Location ID #312624 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1. Tanks and Berms - Open access to wildlife on tank/wildlife hazard/ available for entry by wildlife with a CA date of 12/22/2024
2. Equipment - Gas meter building roof paneling is damaged, also a hole in separator housing/wildlife hazard available for entry by wildlife with a CA date of 12/22/2024
3. Tanks and Berms - Hole in secondary containment liner/liner needs maintenance with a CA date of 01/4/2025

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Produced water label has inaccurate capacity, refer to photos		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign is weathered & cracked but still legible		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	1-800-891-6191/911
Corrective Action:	
	Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe rail fencing		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Gas meter building roof paneling is damaged, also a hole in separator housing/wildlife hazard available for entry by wildlife, refer to photos		
Corrective Action:	Comply with CECMC wildlife rules		Date: 12/22/2024
Type: Bradenhead	#		
Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	Open Top		,
Comment:	Open access to wildlife on tank/wildlife hazard/ available for entry by wildlife, refer to photos				
	Tank not equipped with telemetry				
Corrective Action:	Comply with CECMC wildlife rules				Date: 12/22/2024

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Insufficient		
Comment:	Hole in secondary containment liner/liner needs maintenance, refer to photos			
Corrective Action:	The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs			Date: 01/04/2025

Inspected Facilities									
Facility ID:	222053	Type:	WELL	API Number:	077-08655	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Culverts				
Berms						

Comment: Limited storm water inspection due to snow cover

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Tanks and Berms & Equipment for corrective actions and Signs/Marker for comments.	popejoyd	12/15/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404029455	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6826102
713400544	Inspection Report	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6826101