

Inspection Photos
Location Name: Kammerzell 2-16
Location ID: 322571



Energy & Carbon Management Commission
40.33566, -104.81864, 1416.6m, 343°
12/23/2024 12:44:16

Production facility



Energy & Carbon Management Commission
40.33219, -104.81877, 1428.0m, 358°
12/23/2024 12:37:35

Wellhead

Inspection Photos
Location Name: Kammerzell 2-16
Location ID: 322571



Debris



Debris

Inspection Photos
Location Name: Kammerzell 2-16
Location ID: 322571



Produced water tank placards



Crude oil tank placards