

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/12/2024

Submitted Date:

12/23/2024

Document Number:

699805777**FIELD INSPECTION FORM**Loc ID 312710 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 10310Name of Operator: FRAM OPERATING LLCAddress: 5525 N UNION BLVD #200City: COLORADO State: CO Zip: 80918**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---------------------------|---------|
| De Paolo, Corey | | corey.depaulo@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 277504 | WELL | SI | 04/24/2009 | GW | 077-08872 | DOTY 1-1 (OWP) | PA |

General Comment:[ECMC Inspection Report Summary](#)[On 7/12/2024 I, West OWP Supervisor Corey DePaolo,](#)[Witnessed the plugging and abandonment of the FRAM OPERATING LLC DOTY 1-1 \(OWP\)](#)[Location #312710 in Mesa County Colorado.](#)[-OWP Plugging operations consisted of setting 3 plugs over 2 days. One CIBP, one CICR and surface. The well was cut and capped on 7/12/2024.](#)[This is a summary of the inspection report](#)

| | | | | |
|--|---|--------|--|-----------------|
| Location | | | | |
| Overall Good: <input type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | OTHER | | | |
| Comment: | All signs removed from location | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: _____ |
| Overall Good: <input type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Equipment: | | | | |
| Type: Other | # | | | corrective date |
| Comment: | All equipment has been removed from location. | | | |
| Corrective Action: | | | | Date: |
| Venting: | | | | |
| Yes/No | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Flaring: | | | | |
| Type | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Inspected Facilities | | | | | | | | | | | |
|--------------------------|--------|-------|------|-------------|---|---------|----|---------------|----|-------------------------|----|
| Facility ID: | 277504 | Type: | WELL | API Number: | 077-08872 | Status: | SI | Insp. Status: | PA | | |
| Cement | | | | | | | | | | | |
| Cement Contractor | | | | | | | | | | | |
| Contractor Name: | | | | | Delsco Northwest | | | | | Contractor Phone: | |
| Surface Casing | | | | | | | | | | | |
| Cement Volume (sx): | | | | | | | | | | Circulate to Surface: | |
| Cement Fall Back: | | | | | | | | | | Top Job, 1" Volume: | |
| Intermediate Casing | | | | | | | | | | | |
| Cement Volume (sxs): | | | | | | | | | | Good Return During Job: | |
| Production Casing | | | | | | | | | | | |
| Cement Volume (sx): | | | | | | | | | | Good Return During Job: | |
| Plugging Operations | | | | | | | | | | | |
| Depth Plugs(feet range): | | | | | 1887' to 0' | | | | | Cement Volume (sx): | 57 |
| Good Return During Job: | | | | | YES | | | | | Cement Type: | G |
| Comment: | | | | | OWP Plugging operations consisted of setting 3 plugs over 2 days. One CIBP, one CICR and surface. The well was cut and capped on 7/12/2024. | | | | | | |
| Corrective Action: | | | | | | | | | | Date: | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Berms | | | | | | |

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

| | | |
|---|----------|------------|
| Comment | User | Date |
| Refer to Related Facility for comments, | depaoloc | 12/23/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| | | |
|--------------|-------------|---|
| Document Num | Description | URL |
| 699805778 | Photo Log | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6839907 |