

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/07/2024

Submitted Date:

12/23/2024

Document Number:

699805779

**FIELD INSPECTION FORM**

Loc ID: 334484 Inspector Name: De Paolo, Corey On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

ECMC Operator Number: 10310  
Name of Operator: FRAM OPERATING LLC  
Address: 5525 N UNION BLVD #200  
City: COLORADO State: CO Zip: 80918

**Contact Information:**

Contact Name	Phone	Email	Comment
De Paolo, Corey		corey.depaolo@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277877	WELL	SI	04/24/2009	GW	077-08886	EBERLY 23-4 (OWP)	PA

**General Comment:**

ECMC Inspection Report Summary  
On 6/07/2024 I, West OWP Supervisor Corey DePaolo, Witnessed the plugging and abandonment of the FRAM OPERATING LLC EBERLY#23-4 (OWP) Location #334484 in Mesa County Colorado.  
  
-OWP Plugging operations consisted of setting 2 plugs over 2 days. One CIBP and one CICR. The well was cut and capped on 6/07/2024.  
  
This is a summary of the inspection report

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	All signs have been removed from location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Other	#		corrective date
Comment:	All equipment has been removed from location		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 277877 Type: WELL API Number: 077-08886 Status: SI Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: Delsco Northwest

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 1560' to 0'

Cement Volume (sx): 89

Good Return During Job: YES

Cement Type: G

Comment: OWP Plugging operations consisted of setting 2 plugs over 2 days. One CIBP and one CICR. The well was cut and capped on 6/07/2024.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Refer to related facility for comments</a>	depaoloc	12/23/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805780	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6839908">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6839908</a>