

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/16/2024

Submitted Date:

12/23/2024

Document Number:

699805785

FIELD INSPECTION FORM

Loc ID 322010 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10310
Name of Operator: FRAM OPERATING LLC
Address: 5525 N UNION BLVD #200
City: COLORADO State: CO Zip: 80918

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
De Paolo, Corey		corey.depaolo@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286535	WELL	SI	12/05/2006	GW	029-06100	HAMILTON 33-2 (OWP)	PA

General Comment:

ECMC Inspection Report Summary
On 8/16/2024 I, West OWP Supervisor Corey DePaolo, Witnessed the plugging and abandonment of the FRAM OPERATING LLC HAMILTON#33-2 (OWP) Location #322010 in Delta County Colorado.

-OWP Plugging operations consisted of setting 3 plugs over 2 days. Two CIBP and surface. The well was cut and capped on 8/16/2024.

This is a summary of the inspection report

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	All signs removed from location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

			corrective date
Type: Other	#		
Comment:	All equipment has been removed from location		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 286535 Type: WELL API Number: 029-06100 Status: SI Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Delsco Northwest

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 2832' to 0'

Cement Volume (sx): 138

Good Return During Job: YES

Cement Type: G

Comment: OWP Plugging operations consisted of setting 3 plugs over 2 days. Two CIBP and surface. The well was cut and capped on 8/16/2024.

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Refer to related facility for comments	depaoloc	12/23/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805786	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6839911