

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/15/2024

Submitted Date:

12/24/2024

Document Number:

699805799

**FIELD INSPECTION FORM**Loc ID 334471 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

ECMC Operator Number: 10310

Name of Operator: FRAM OPERATING LLC

Address: 5525 N UNION BLVD #200

City: COLORADO State: CO Zip: 80918

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
De Paolo, Corey		corey.depaulo@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268397	WELL	SI	09/14/2012	GW	077-08794	LOUGH 36-1 (OWP)	PA

**General Comment:**

ECMC Inspection Report Summary

On 8/15/2024 I, West OWP Supervisor Corey DePaolo,

Witnessed the plugging and abandonment of the FRAM OPERATING LLC Lough 36-1 (OWP)

Location #334471 in Mesa County Colorado.

-OWP Plugging operations consisted of setting 3 plugs over 2 days. One CIBP, one CICR and surface. The well was cut and capped on 8/15/2024.

This is a summary of the inspection report

Location				
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type OTHER				
Comment: All signs have been removed from location				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Other		#		corrective date
Comment: All equipment has been removed from location				
Corrective Action:				Date:
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	268397	Type:	WELL	API Number:	077-08794	Status:	SI	Insp. Status:	PA
Cement									
Cement Contractor									
Contractor Name:		Delsco Northwest		Contractor Phone:					
Surface Casing									
Cement Volume (sx):				Circulate to Surface:					
Cement Fall Back:				Top Job, 1" Volume:					
Intermediate Casing									
Cement Volume (sxs):				Good Return During Job:					
Production Casing									
Cement Volume (sx):				Good Return During Job:					
Plugging Operations									
Depth Plugs(feet range):		2940' to 0'		Cement Volume (sx):		70			
Good Return During Job:		YES		Cement Type:		G			
Comment:		OWP Plugging operations consisted of setting 3 plugs over 2 days. One CIBP, one CICR and surface. The well was cut and capped on 8/15/2024.							
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<a href="#">Refer to related facility for comments</a>	depaoloc	12/24/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805800	Photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6852104">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6852104</a>