

# Interim Reclamation and Stormwater Inspection

December 16, 2024

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 318979

Well Name: DORIS #12-34

Inspection Document #: 718600084

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: DORIS #12-34  
Location ID: 318979



**Photo 1.** Photo taken Looking west along access road. Deep ruts in access road have resulted in widening of access road.



**Photo 2.** Looking east across well site. Undesirable weedy plant species are present on location.

Inspection Photos  
Location Name: DORIS #12-34  
Location ID: 318979



**Photo 3.** Wellbore is leaking. Stained soil is present around wellbore.



**Photo 4.** Stained soil present around engine. Close engine shed door to prevent unauthorized access. Flywheel does not have cover installed.



Inspection Photos  
Location Name: DORIS #12-34  
Location ID: 318979



**Photo 5.** Trash and unused equipment being stored in and out of secondary containment.



**Photo 6.** Broken belts left in place around pulley.



Inspection Photos  
Location Name: DORIS #12-34  
Location ID: 318979



**Photo 7.** Looking northwest across tank battery. Weedy annual plant species were present throughout location (Kochia, Russian thistle).



**Photo 8.** Uncapped pipes and trash at tank battery.



Inspection Photos  
Location Name: DORIS #12-34  
Location ID: 318979



**Photo 9.** Looking south across tank battery. This tank battery location is shared with Dottie Doris #11, 12-34 (Loc # 464916) See Photo 7 comments.

Inspection Photos  
Location Name: DORIS #12-34  
Location ID: 318979



Photo 10. Unused equipment (pipe) near separator.



Photo 11. Trash and weeds are present near separator.

