

Interim Reclamation and Stormwater Inspection

December 16, 2024

Operator: DCP OPERATING COMPANY LP - 4680

Location ID: 464916

Inspection Document #: 718600086

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Dottie Doris/11,12-34
Location ID: 464916



Photo 1. Proposed monitoring well holes appear to have been dug.



Photo 2. See Photo 1 comments.

Inspection Photos
Dottie Doris/11,12-34
Location ID: 464916



Photo 4. Unlabeled barrels potentially associated with groundwater monitoring project.



Photo 5. Photo taken west of Dottie-Doris separator looking south.

Inspection Photos
 Dottie Doris/11,12-34
 Location ID: 464916



DATE: November 2024 DESIGNED BY: B. Humphrey DRAWN BY: J. Wolfenden	 TASMAN GEOSCIENCES Tasman Geosciences, Inc. 6855 W. 119th Ave Broomfield, CO 80020	DCP Operating, LP / Phillips 66 CR55 and CR4 (AT-1-1-1-6-3) 5/2023 SWNW Section 34, Township 1 North, Range 64 West Weld County, Colorado	Site Overview and Proposed Monitoring Well Location Map	FIGURE 1
---	---	--	--	-------------

Photo 5. Operator submitted site map of current and future monitoring wells.



Inspection Photos
Dottie Doris/11,12-34
Location ID: 464916



Photo 6. Looking south from east of the tank battery.

Inspection Photos
Dottie Doris/11,12-34
Location ID: 464916



Photo 7. Monitoring wells in place. Photo looking south near MW-03.

Inspection Photos
Dottie Doris/11,12-34
Location ID: 464916



Photo 8. Photo looking northwest near MW-06.