

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WARE SR 23-12 Pad

Location ID: 449385



Photo # 5263 From entrance to location




Photo # 5264 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WARE SR 23-12 Pad

Location ID: 449385



Photo # 5265 Location



Photo # 5266 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WARE SR 23-12 Pad

Location ID: 449385



Photo # 5267 Location



Photo # 5268 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WARE SR 23-12 Pad

Location ID: 449385



Photo # 5269 Location



Photo # 5270 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WARE SR 23-12 Pad

Location ID: 449385



Photo # 5271 Location



Photo # 5272 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WARE SR 23-12 Pad

Location ID: 449385



Photo # 5273 Location



Photo # 5274 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WARE SR 23-12 Pad

Location ID: 449385



Photo # 5275 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 5276 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WARE SR 23-12 Pad

Location ID: 449385



Dec 24, 2024 at 11:44:56 AM

Photo # 5277 PRV vent line does not comply with CECMC pressure safety device rules



Dec 24, 2024 at 11:45:00 AM

Photo # 5278 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WARE SR 23-12 Pad

Location ID: 449385



Photo # 5279 Secondary containment liner showing signs of damage/disrepair near top of metal containment ring



Photo # 5280 Secondary containment liner showing signs of damage/disrepair near top of metal containment ring