



FORM
INSP

Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
12/18/2024
Submitted Date:
12/18/2024
Document Number:
708303220

Loc ID
335521

Inspector Name:
Morris, Matthew

On-Site Inspection ☐
2A Doc Num: _____

Operator Information:

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:
12 Number of Comments
1 Number of Corrective Actions
☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Smelser, Wayne		wayne.smelser@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297301	WELL	PR	04/22/2009	GW	045-16382	JCJ 22C-21-692	PR
297476	WELL	PR	04/08/2009	GW	045-16854	JCJ 11A-21-692	PR
297477	WELL	PR	04/20/2009	GW	045-16855	JCJ 21B-21-692	PR
297478	WELL	PR	04/20/2009	GW	045-16856	JCJ 21A-21-692	PR
297479	WELL	PR	03/26/2009	GW	045-16857	JCJ 12D-21-692	PR
297480	WELL	PR	03/25/2009	GW	045-16858	JCJ 12C-21-692	PR
297481	WELL	PR	03/26/2009	GW	045-16859	JCJ 12B-21-692	PR
297482	WELL	PR	03/30/2009	GW	045-16860	JCJ 12A-21-692	PR
297483	WELL	PR	04/09/2009	GW	045-16861	JCJ 11D-21-692	PR
297484	WELL	PR	04/09/2009	GW	045-16862	JCJ 11C-21-692	PR
297485	WELL	PR	03/25/2009	GW	045-16863	JCJ 11B-21-692	PR
297486	WELL	PR	04/22/2009	GW	045-16864	JCJ 22D-21-692	PR
297487	WELL	PR	04/22/2009	GW	045-16865	JCJ 22B-21-692	PR
297488	WELL	PR	04/09/2009	GW	045-16866	JCJ 22A-21-692	PR
297489	WELL	PR	04/08/2009	GW	045-16867	JCJ 21D-21-692	PR
297490	WELL	PR	04/13/2009	GW	045-16868	JCJ 21C-21-692	PR

General Comment:

Date Run: 12/25/2024 Doc [#708303220]

Page 1 of 10

CECMC Inspection Report Summary

On 12/18/2024 at approximately 12:45, Compliance Inspector Matthew Morris conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC, JCJ-66S92W/21SEW at Location ID #335521 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

1) Illegible tank label

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

LocationOverall Good: ☐

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Illegible label on produced water tank.		
Corrective Action:	Install label to comply with Rule 605.h.	Date:	01/18/2025
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-9377

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	OTHER		

Comment:	Gas lift manifold and heater treater protected by cattle panels.			Date:	
Corrective Action:				Date:	
Equipment:				corrective date	
Type: Gas Meter Run	# 16				
Comment:	Gas lift manifold			Date:	
Corrective Action:				Date:	
Type: Ancillary equipment	# 4				
Comment:	Chemical tanks			Date:	
Corrective Action:				Date:	
Type: Horizontal Heater Treater	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	Liquid nitrogen tank			Date:	
Corrective Action:				Date:	
Type: Bird Protectors	# 14				
Comment:				Date:	
Corrective Action:				Date:	
Type: Gas Meter Run	# 16				
Comment:				Date:	
Corrective Action:				Date:	
Type: Bradenhead	# 16				
Comment:				Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 16				
Comment:				Date:	
Corrective Action:				Date:	
Type: Emission Control Device	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Plunger Lift	# 16				
Comment:				Date:	
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	500 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 297301	Type: WELL	API Number: 045-16382	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 297476	Type: WELL	API Number: 045-16854	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 297477	Type: WELL	API Number: 045-16855	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 297478	Type: WELL	API Number: 045-16856	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 297479	Type: WELL	API Number: 045-16857	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 297480	Type: WELL	API Number: 045-16858	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 297481	Type: WELL	API Number: 045-16859	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 297482	Type: WELL	API Number: 045-16860	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

<u>Producing Well</u>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	297483	Type:	WELL	API Number: 045-16861 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	297484	Type:	WELL	API Number: 045-16862 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	297485	Type:	WELL	API Number: 045-16863 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	297486	Type:	WELL	API Number: 045-16864 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	297487	Type:	WELL	API Number: 045-16865 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	297488	Type:	WELL	API Number: 045-16866 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	297489	Type:	WELL	API Number: 045-16867 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				

Corrective Action:		Date:							
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	297490	Type:	WELL	API Number:	045-16868	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Gravel				
		Compaction				
Compaction						
				Material Handling And Spill Prevention		
		Culverts				
Berms						
Gravel						
Ditches						

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404034651	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6831463
708303221	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6831450