

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough RWF 12-20 Tank Pad

Location ID: 457490



Photo # 4968 From entrance to location




Photo # 4969 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough RWF 12-20 Tank Pad

Location ID: 457490



Dec 23, 2024 at 12:19:27 PM
CO

Photo # 4970 Location



Dec 23, 2024 at 12:11:21 PM
CO

Photo # 4971 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough RWF 12-20 Tank Pad

Location ID: 457490



Photo # 4972 Location



Photo # 4973 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough RWF 12-20 Tank Pad

Location ID: 457490



Photo # 4974 Location



Photo # 4975 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough RWF 12-20 Tank Pad

Location ID: 457490



Photo # 4976 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 4977 Pickup truck parked on location