

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/25/2024

Submitted Date:

12/26/2024

Document Number:

699805823**FIELD INSPECTION FORM**Loc ID 334483 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 10310Name of Operator: FRAM OPERATING LLCAddress: 5525 N UNION BLVD #200City: COLORADO State: CO Zip: 80918**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
De Paolo, Corey		corey.depaulo@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291561	WELL	SI	07/25/2009	GW	077-09350	WHITING 26-5 (OWP)	PA

**General Comment:**[ECMC Inspection Report Summary](#)[On 7/25/2024 I, West OWP Supervisor Corey DePaolo,](#)[Witnessed the plugging and abandonment of the FRAM OPERATING LLC Whiting 26-5 \(OWP\)](#)[Location #334483 in Mesa County Colorado.](#)[-OWP Plugging operations consisted of setting 3 plugs over 2 days. One CIBP, one CICR and surface. The well was cut and capped on 7/25/2024.](#)[This is a summary of the inspection report](#)

Location				
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	OTHER			
Comment:	All sign removed from location			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Other	#			corrective date
Comment:	All equipment removed from location			
Corrective Action:				Date:
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	291561	Type:	WELL	API Number:	077-09350	Status:	SI	Insp. Status:	PA
Cement									
Cement Contractor									
Contractor Name: Delsco Northwest					Contractor Phone:				
Surface Casing									
Cement Volume (sx):					Circulate to Surface:				
Cement Fall Back:					Top Job, 1" Volume:				
Intermediate Casing									
Cement Volume (sxs):					Good Return During Job:				
Production Casing									
Cement Volume (sx):					Good Return During Job:				
Plugging Operations									
Depth Plugs(feet range): 1350' to 0'					Cement Volume (sx): 70				
Good Return During Job: YES					Cement Type: G				
Comment: OWP Plugging operations consisted of setting 3 plugs over 2 days. One CIBP, one CICR and surface. The well was cut and capped on 7/25/2024.									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<a href="#">Refer to related facility for comments</a>	depaoloc	12/26/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805824	Photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6853981">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6853981</a>