

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/06/2024

Submitted Date:

12/20/2024

Document Number:

717900122**FIELD INSPECTION FORM**Loc ID 336506 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|---------------------------------|
| , | | cogccinspections@oxy.com | |
| , | | ECMCInspections@Oxy.com | All Inspections |

General Comment:

This is an environmental inspection for Location ID 336506 Vonderlage WH. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

| | | | | | |
|--|---|---|--|-------------|--|
| Location | | | | | |
| Overall Good: <input type="checkbox"/> | | | | | |
| Emergency Contact Number: | | | | | |
| Comment: | | | | Date: _____ | |
| Corrective Action: | | | | | |
| Overall Good: <input checked="" type="checkbox"/> | | | | | |
| Spills: | | | | | |
| Type | Area | Volume | | | |
| In Containment: No | | | | | |
| Comment: | | No spills observed during inspection. Adjacent Snella well has been P&A'd and is currently and open excavation. | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | | |
| Fencing/: | | | | | |
| Type | | | | | |
| Comment: | Cattle fencing surrounding open wellhead excavation appears to be functional. | | | | |
| Corrective Action: | | | | Date: | |
| Venting: | | | | | |
| Yes/No | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Location Construction

Location ID: 336506 CDP: _____

Comment: Adjacent Snella well is under decommissioning and has been removed. Soil stock pile is on site but is not contained by berms.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment:

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment:

Corrective Action: _____ Date: _____

Comment: Soil stock pile on site, but is not contained by berms or liner.

Corrective Action: Soil stock pile needs to be conatined by berms or wattles to prevent soil migration in the case of a precipitation event. Install or repair required BMPs per Rule 1002.f.(2)C

Date: 01/03/2025

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental

Spills/Releases:

Type of Spill:Estimated Spill Volume:

Comment:

No spills or releases were observed during the inspection.

Corrective Action:

Date:

Reportable:GPS: LatLong

Proximity to Surface Water:Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num:Owner Name:GPS :

LatLong

Field Parameters:

Sample Location:Comment:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404037508 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6836950 |
| 717900123 | photo log | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6836946 |