

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/12/2024

Submitted Date:

12/20/2024

Document Number:

718600082**FIELD INSPECTION FORM**Loc ID 322211 Inspector Name: Dunnam, Anthony On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10634Name of Operator: P O & G OPERATING LLCAddress: 5847 SAN FELIPE SUITE 3200City: HOUSTON State: TX Zip: 77057**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name       | Phone        | Email                              | Comment         |
|--------------------|--------------|------------------------------------|-----------------|
| MOORE, CHRISTOPHER | 713-244-0779 | christopher_moore@pogresources.com | Principal Agent |

**Inspected Facilities:**

| Facility ID | Type     | Status | Status Date | Well Class | API Num   | Facility Name                             | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|---|-------------|
| 209736      | WELL     | PA     | 12/19/2016  | OW         | 039-06641 | CANYON ENERGY STATE ALBERTA 36-24         | RI          |
| 322211      | LOCATION | CL     |             |            | -         | CANYON ENERGY STATE ALBERTA-68S59W 36SESW | RI          |

**General Comment:**

This is a Final Reclamation Inspection for PA Well API#039-06641, Location Id 322211. Well was plugged and abandoned 12/19/2016.

The tank battery location will be inspected at a future date.

|  |  |        |  |             |
|--|--|--------|--|-------------|
| Location   |  |        |  |             |
| Overall Good: <input type="checkbox"/>                 |  |        |  |             |
| Emergency Contact Number:                              |  |        |  |             |
| Comment:   |  |        |  | Date: _____ |
| Corrective Action:                                     |  |        |  |             |
| Good Housekeeping:                                     |  |        |  |             |
| Type   | TRASH  |        |  |             |
| Comment:   | Trash including hose, pipe and plastic fittings remain on location.<br>Comply with rule 606.d. |        |  |             |
| Corrective Action:                                     |  |        |  | Date:       |
| Overall Good: <input type="checkbox"/>                 |  |        |  |             |
| Spills:  |  |        |  |             |
| Type   | Area   | Volume |  |             |
| In Containment: No                                     |  |        |  |             |
| Comment:   |  |        |  |             |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |  |             |
| Venting:   |  |        |  |             |
| Yes/No   |  |        |  |             |
| Comment:   |  |        |  |             |
| Corrective Action:                                     |  |        |  | Date:       |
| Flaring:   |  |        |  |             |
| Type   |  |        |  |             |
| Comment:   |  |        |  |             |
| Corrective Action:                                     |  |        |  | Date:       |

| Inspected Facilities   |        |       |          |             |           |         |    |               |    |
|--|--------|-------|----------|-------------|-----------|---------|----|---------------|----|
| Facility ID:   | 209736 | Type: | WELL     | API Number: | 039-06641 | Status: | PA | Insp. Status: | RI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |          |             |           |         |    |               |    |
| Facility ID:   | 322211 | Type: | LOCATION | API Number: | -         | Status: | CL | Insp. Status: | RI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |          |             |           |         |    |               |    |

| Environmental                              |   |
|--|---|
| <b>Spill/Remediation:</b>                  |   |
| Comment:                                   | <a href="#">All spills/releases have been closed, as well as the associated pits under Remediation project #3943.</a> |
| Corrective Action:                         | <div></div> <div>Date: <div></div></div>  |
| Emission Control Burner (ECB): <div></div> |   |
| Comment: <div></div>                       |   |
| Pilot: <div></div>                         | Wildlife Protection Devices (fired vessels): <div></div>  |

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started:                      Date Interim Reclamation Completed:                     

Land Use:                     

Comment:                     

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING                     

Comment                     

Corrective Action                      Date                     

1002b. SOIL REMOVAL AND  
SEGREGATION                     

Comment                     

Corrective Action                      Date                     

1002c. PROTECTION OF SOILS                     

Comment                     

Corrective Action                      Date                     

1002E. SURFACE DISTRURBANCE MINIMIZATION                     

Comment                     

Corrective Action                      Date                     

1003a. Waste and Debris removed?                     

Comment                     

Corrective Action                      Date                     

Unused or unneeded equipment onsite?                     

Comment                     

Corrective Action                      Date                     

Pit, cellars, rat holes and other bores closed?                     

Comment                     

Corrective Action                      Date                     

Guy line anchors marked?                     

Comment                     

Corrective Action                      Date

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed **Fail** No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded **Fail** Contoured **Fail** Culverts removed \_\_\_\_\_

Gravel removed **Fail**

Location and associated production facilities reclaimed **Fail** Locations, facilities, roads, recontoured **Fail**

Compaction alleviation **Fail** Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present **Fail** Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: **This location does not comply with Rule 1004. Reclamation rules require reclamation activities to be conducted within twelve months of plugging on non-cropland. Well was plugged 12/19/2016. It does not appear any reclamation work has been performed; gravel remains throughout the location and access roads which have not been re-contoured or re-graded; weedy, annual vegetation was observed which includes but not limited to cheatgrass, russian thistle and kochia.**

|                           |   |   |
|---------------------------|---|---|
| Corrective Action:        | Comply with Rule 1004. Remove all gravel. Perform compaction alleviation to a depth of 18 inches. Regrade and recontour access road and location. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management. | Date  |
| Overall Final Reclamation | Fail  | Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/> |

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: At the time of this inspection, no stormwater erosion issues were observed at location or along the access road.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 404036556    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6836064">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6836064</a> |
| 718600083    | Inspection Photos    | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6836061">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6836061</a> |