

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/16/2024

Submitted Date:

12/20/2024

Document Number:

707801286**FIELD INSPECTION FORM**Loc ID 398837 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, QB		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301780	WELL	PR	12/01/2023	GW	103-11474	PICEANCE CREEK UNIT 296-6A10	PR
301781	WELL	PR	09/26/2011	GW	103-11475	PICEANCE CREEK UNIT 296-6A1	PR
301783	WELL	SI	09/01/2024	GW	103-11477	PICEANCE CREEK UNIT 296-6A6	SI
301784	WELL	PR	09/01/2023	GW	103-11478	PICEANCE CREEK UNIT 296-6A5	PR
301785	WELL	PR	12/01/2023	GW	103-11479	PICEANCE CREEK UNIT 296-6A8	PR
301786	WELL	PR	12/01/2011	GW	103-11480	PICEANCE CREEK UNIT 296-6A4	PR
301787	WELL	PR	09/01/2023	GW	103-11481	PICEANCE CREEK UNIT 296-6A3	PR
301788	WELL	PR	11/15/2011	GW	103-11482	PICEANCE CREEK UNIT 296-6A7	PR
301789	WELL	PR	02/01/2023	GW	103-11483	PICEANCE CREEK UNIT 296-6A9	PR

General Comment:

ECMC Inspection Report Summary

On Monday 12/16/2024, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus PCU 296-6A, at Location # 398837 in Rio Blanco county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Well signage lacks proper information

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Well signage lacks proper information		
Corrective Action:	Provide proper well signage	Date:	01/31/2025
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action: _____ Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Separator	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 9		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	3 chemical tanks and 1 500 gallon methanol tank		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities			
Facility ID: 301780	Type: WELL	API Number: 103-11474	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 301781	Type: WELL	API Number: 103-11475	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 301783	Type: WELL	API Number: 103-11477	Status: SI Insp. Status: SI
Idle Well			
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned	Reminder: _____		
Comment: Last produced 9/2024			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 301784	Type: WELL	API Number: 103-11478	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 301785	Type: WELL	API Number: 103-11479	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 301786	Type: WELL	API Number: 103-11480	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 301787	Type: WELL	API Number: 103-11481	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Facility ID:	301788	Type:	WELL	API Number:	103-11482	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	301789	Type:	WELL	API Number:	103-11483	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

--	--	--	--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited storm water inspection due to snow cover.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404037579	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6837052
707801291	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6837035