

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/16/2024

Submitted Date:

12/20/2024

Document Number:

713400567

**FIELD INSPECTION FORM**

Loc ID 335083 Inspector Name: Popejoy, Dusty On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 27 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Smelser, Wayne		wayne.smelser@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277912	WELL	PR	11/01/2014	GW	045-10809	GUCCINI 41D-20-692	PR
277913	WELL	PR	06/07/2006	GW	045-10810	GUCCINI 41B-20-692	PR
277914	WELL	PR	06/07/2006	GW	045-10811	GUCCINI 31D-20-692	PR
277915	WELL	PR	06/05/2006	GW	045-10812	GUCCINI 31B-20-692	PR
290198	WELL	PR	08/01/2024	GW	045-14053	GUCCINI 31A-20-692	PR
290200	WELL	PR	04/17/2012	GW	045-14052	GUCCINI 41C-20-692	PR
290202	WELL	PR	09/05/2007	GW	045-14051	GUCCINI 31C-20-692	PR
290203	WELL	PR	09/05/2007	GW	045-14050	GUCCINI 41A-20-692	PR

**General Comment:**

[CECMC Inspection Report Summary](#)

On 12/16/2024 at approximately 16:22 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC GUCCINI Pad at Location ID #335083 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

- 1. 2 PRV vent lines do not comply with CECMC pressure safety device rules with a CA date of 12/27/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Production tanks for wells are located on the CB-TG Land Pad, location #418555

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Access		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	970-285-9377/911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Debris - refer to photos		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Chemical tanks - Livestock panels		
Corrective Action:			Date:
Type	OTHER		
Comment:	Pig station - pipe rail fence		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Livestock panels		

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	<a href="#">Hog panels</a>		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 8		
Comment:	<a href="#">All wells on plunger lift</a>		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	<a href="#">Liquid nitrogen tank</a>		
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:	<a href="#">All Bradenhead valves are accessible - Guccini 31B bradenhead is equipped with telemetry for monitoring</a>		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	<a href="#">PRV vent lines do not comply with CECMC pressure safety device rules, refer to photos</a>		
Corrective Action:	<a href="#">Comply with CECMC pressure safety device rules</a>	Date:	<u>12/27/2024</u>
Type: Ancillary equipment	# 3		
Comment:	<a href="#">Chemical tanks</a>		
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	277912	Type:	WELL	API Number:	045-10809	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	277913	Type:	WELL	API Number:	045-10810	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	277914	Type:	WELL	API Number:	045-10811	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	277915	Type:	WELL	API Number:	045-10812	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	290198	Type:	WELL	API Number:	045-14053	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	290200	Type:	WELL	API Number:	045-14052	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	290202	Type:	WELL	API Number:	045-14051	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift							Date:	
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290203 Type: WELL API Number: 045-14050 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Gravel				Sparse
Ditches						
Rip Rap						
		Rip Rap				
		Ditches				
		Compaction				
				Material Handling And Spill Prevention		Chemical tank containments
Berms						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Equipment for corrective action and Housekeeping for comments.</a>	popejoyd	12/20/2024
<a href="#">Production tanks for wells are located on the CB-TG Land Pad, location #418555</a>		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404037733	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6837368">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6837368</a>
713400568	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6837367">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6837367</a>