

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Burckle/A Pad

Location ID: 335540

Date: 12/23/2024



Location Entrance – Photo #05541



Location – Photo #05544

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC, Burckle/A Pad
Location ID: 335540
Date: 12/23/2024

Location Name: TEP ROCKY MOUNTAIN LLC, Burckle/A Pad

Location ID: 335540

Date: 12/23/2024



Location – Photo #05543



Location – Photo #05546

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Burckle/A Pad

Location ID: 335540

Date: 12/23/2024



Location – Photo #05549



Location – Photo #05545

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Burckle/A Pad

Location ID: 335540

Date: 12/23/2024



Weathered Tank Label Needs Replaced – Photo #05556



Stored Supplies/Wildlife Entry Hazard – Photo #05553

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Burckle/A Pad

Location ID: 335540

Date: 12/23/2024



Stored Supplies/Wildlife Entry Hazard – Photo #05560



Open-Ended Line on Tank – Photo #05559

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Burckle/A Pad

Location ID: 335540

Date: 12/23/2024



Rill Erosion Undercutting BMP – Photo #05564



Rill Erosion Undercutting BMP – Photo #05562