

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/27/2024

Submitted Date:

12/28/2024

Document Number:

707603449

FIELD INSPECTION FORM

Loc ID: 302231 Inspector Name: Evins, Bret On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287168	WELL	TA	05/04/2020	GW	123-27389	CECIL USX AB 35-14	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Battery: Abandoned. ALL equipment removed.
Abandoned Battery SE corner GPS coordinates: 40.526480 / -104.523320

Abandoned Centralized Battery formerly served 3 Location IDs (422514, 302231, 306371).
(Well(s): 4: Plugged & Abandoned | PA).

Reference (Associated Well(s) Inspections):
A.) Field Inspection Report doc. #707603445 and/or Location ID #422514 for PA Well(s) info.
B.) Field Inspection Report doc. #707603447 and/or Location ID #422514 for PA Well(s) info.
C.) Field Inspection Report doc. #707603449 and/or Location ID #302231 for PA Well(s) info.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Plunger Lift

0

corrective date

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 287168 Type: WELL API Number: 123-27389 Status: TA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On FRI 12/27/2024 at approximately 11:42 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: CECIL USX AB-67N64W/35SESW Location ID: 302231 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. and/or photo(s) #1 attached to this report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment removed. Abandoned Battery SE corner GPS coordinates: 40.526480 / -104.523320</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6-SRA on file. Plugging, cut/cap date: 11/08/2024. Approval Pending. Plugged & Abandoned PA well GPS coordinates: 40.523867 / -104.520241</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	12/28/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603450	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6855687