

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/24/2024

Submitted Date:

12/28/2024

Document Number:

708905351

FIELD INSPECTION FORM

Loc ID 311663 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

39 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287101	WELL	PR	07/31/2008	GW	045-12867	FEDERAL RMV 142-9	PR
287102	WELL	PR	10/27/2008	GW	045-12866	FEDERAL RWF 423-9	PR
287103	WELL	PR	10/24/2008	GW	045-12865	FEDERAL RWF 523-9	PR
287104	WELL	PR	07/30/2008	GW	045-12864	FEDERAL RWF 324-9	PR
287105	WELL	PR	10/14/2013	GW	045-12863	FEDERAL RWF 424-9	PR
287106	WELL	PR	10/22/2008	GW	045-12862	FEDERAL RWF 323-9	PR
287107	WELL	PR	04/01/2023	GW	045-12861	FEDERAL RWF 334-9	PR
287108	WELL	PR	06/14/2007	GW	045-12860	FEDERAL RWF 434-9	PR
287109	WELL	PR	07/01/2023	GW	045-12859	FEDERAL RWF 33-9	PR
287110	WELL	PR	08/01/2022	GW	045-12858	FEDERAL RWF 433-9	PR
287111	WELL	PR	12/01/2022	GW	045-12857	FEDERAL RWF 333-9	PR
287112	WELL	PR	07/11/2008	GW	045-12856	FEDERAL RWF 34-9	PR
287113	WELL	PR	07/31/2008	GW	045-12855	FEDERAL RWF 534-9	PR

General Comment:

CECMC Inspection Report Summary

On 12/24/2024 at approximately 10:47 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC FEDERAL RWF 324-9 Pad.

Location # 311663 in Garfield County Colorado.

Please refer to inspection 708904985 conducted on 11/07/2024, previous corrective actions have been completed.

Location is within High Priority/Density Habitat areas & in close proximity to NSO Habitat area.

Location is approximately 15 yards from a creek that contributes to the Colorado River.

While there, I observed normal production operations.

This is a summary of inspection report.

Any corrective actions from previous inspections that have not been addressed are still applicable.

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Some signs starting to weather & crack		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:

Emergency Contact Number:		
Comment:	911/970-285-9377	
Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Chemical tank - hog panels		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:

Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:
Type	OTHER		
Comment:	Sand trap - hog panels		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:

Equipment:			corrective date
Type: Horizontal Heated Separator	# 13		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 13		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank Unable to locate FORM 4 SUNDRY for equipment		
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:	Marked		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Sand trap		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:			Date:
Type: Bradenhead	# 13		
Comment:	RWF 33-9 well has pressure transducer & Taylor plug located on bradenhead, bradenhead valve is accessible. Remaining 12 wells have Taylor plugs located on bradenheads, bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Gas Meter Run	# 13		
Comment:			
Corrective Action:			Date:

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	STEEL AST		,	
Comment: Tank equipped with telemetry						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity) 80 bbl						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient				
Comment: Separate containment						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST		,	
Comment: FORM 4 SUNDRY document #'s 401602131 & 401628491 Tank equipped with telemetry						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient				
Comment: Separate containment						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	287101	Type:	WELL	API Number:	045-12867	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift				Date:				
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	287102	Type:	WELL	API Number:	045-12866	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift				Date:				
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	287103	Type:	WELL	API Number:	045-12865	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift				Date:				
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	287104	Type:	WELL	API Number:	045-12864	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift				Date:				
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	287105	Type:	WELL	API Number:	045-12863	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift				Date:				
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	287106	Type:	WELL	API Number:	045-12862	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift				Date:				
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	287107	Type:	WELL	API Number:	045-12861	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift				Date:				
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	287108	Type:	WELL	API Number:	045-12860	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift				Date:				
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287109 Type: WELL API Number: 045-12859 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287110 Type: WELL API Number: 045-12858 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287111 Type: WELL API Number: 045-12857 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287112 Type: WELL API Number: 045-12856 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287113 Type: WELL API Number: 045-12855 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Sediment Traps				
Culverts						
Sediment Traps						
Rip Rap						
		Gravel				Sparse to none in sections
		Rip Rap				
Ditches						
Compaction	Fail					Lack of stabilization/compaction
				Material Handling And Spill Prevention		Chemical tank containment
		Ditches				
		Compaction				
Gravel						Sparse to none in areas
		Culverts				

Comment: Lack of stabilization/compaction on location (NE area of pad near tank battery)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Equipment & Stormwater for comments	smelserw	12/28/2024
Any corrective actions from previous inspections that have not been addressed are still applicable.		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708905352	Inspection 708905351 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6855699
708905353	Inspection 708905351 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6855700