

## Inspection Photos

Location Name: PETTINGER-USX AB-67N64W/35SENE

Location ID: 306362



**Photo #1**

**Pettinger USX AB 35-8, 35-01D** Battery site

**Inactive | Shut-down**

*Battery site entrance*



**Photo #2**

**Pettinger USX AB 35-8, 35-01D** Battery site

**Inactive | Shut-down**

*Formerly served:*

*Pettinger USX AB 35-02, 35-7;*

*Plugged & Abandoned | PA*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: PETTINGER-USX AB-67N64W/35SENE

Location ID: 306362



**Photo #3**

**Pettinger USX AB 35-8, 35-01D Battery site**

**Inactive | Shut-down**

*Crude oil, produced H<sub>2</sub>O tank(s): SE corner*



**Photo #4**

**Pettinger USX AB 35-8, 35-01D Battery site**

**Inactive | Shut-down**

*ECD(s), Separator(s)*



**COLORADO**  
**Energy & Carbon Management**  
**Commission**  
Department of Natural Resources



## Inspection Photos

Location Name: PETTINGER-USX AB-67N64W/35SENE

Location ID: 306362



**Photo #5**

**Pettinger USX AB 35-8, 35-01D Battery site**

**Inactive | Shut-down**

*Battery sign*



**COLORADO**  
**Energy & Carbon Management**  
**Commission**

Department of Natural Resources

## Inspection Photos

**Location Name:** PETTINGER-USX AB-67N64W/35SENE

**Location ID:** 306362

Associated Well(s)	API	Status
1. Pettinger-USX AB 35-8	123-24535	TA
2. Pettinger USX AB 35-01D	123-33039	TA

### Photo #6

**Pettinger USX AB 35-8, 35-01D** Battery site

**Inactive | Shut-down**

**Associated Well(s):**

**2: Temporarily Abandoned | TA**



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources