

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/27/2024

Submitted Date:

12/28/2024

Document Number:

707603457

FIELD INSPECTION FORM

Loc ID 306362 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288186	WELL	TA	02/09/2022	OW	123-24535	PETTINGER-USX AB 35-8	TA

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (306362, 421746).
(Well(s): 2: Temporarily Abandoned | TA; 1: Plugged & Abandoned | PA).

Centralized Battery Formerly served 1 Location ID (302234).
(Well(s): 1: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery Inspections):
A.) Field Inspection Report doc. #707603457 and/or Location ID #306362 for TA Well(s) info.
B.) Field Inspection Report doc. #707603459 and/or Location ID #421746 for TA Well(s) info.
C.) Field Inspection Report doc. #707603461 and/or Location ID #302234 for PA Well(s) info.
D.) Field Inspection Report doc. #707603463 and/or Location ID #421746 for PA Well(s) info.
E.) Field Inspection Report doc. #707603465 and/or Facility ID #306362 for Battery / Facility, Equipment info.

Location

Lease Road:			
	Type	Access	
	comment:	Adequate	
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type	WELLHEAD	
	Comment:	OOSLAT applied.	
Corrective Action:			Date:

Emergency Contact Number:			
	Comment:		
	Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type	WELLHEAD	
	Comment:	Iron panel.	
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 0		
	Comment:	Temporarily Abandoned TA. Equipment removed.	
Corrective Action:			Date:
Type: Bradenhead	# 1		
	Comment:	Appears plumbed to surface.	
Corrective Action:			Date:
Type: Other	# 1		
	Comment:	Wellhead: w/ Master, casing valves.	
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.532196,-104.507881

Comment:	Centralized Battery serves 2 Location IDs (306362, 421746). (Well(s): 2: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).	
Corrective Action:		Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 288186 Type: WELL API Number: 123-24535 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Disconnected from flowline.
Locked-Out, Tagged-Out | LOTO.
OOSLAT applied at well, separator.
CECMC records last production: 02/2020.

Form 21 MIT on file. MIT date: 01/26/2022. Approved.
DH-CIBP.
Form 6A on file. Out of Service Designation.
Date Ceased prod: 02/16/2020. Approved.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 01/27/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On FRI 12/27/2024 at approximately 12:57 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: PETTINGER-USX AB-67N64W/35SENE Location ID: 306362 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	12/28/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603458	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6855740