



FORM
INSP

Rev
X/20

State of Colorado
Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
12/20/2024
Submitted Date:
12/20/2024
Document Number:
699506738

Loc ID
320021

Inspector Name:
MEDINA, JUSTIN

On-Site Inspection ☐
2A Doc Num:

Operator Information:
ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Status Summary:
☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:
4 Number of Comments
0 Number of Corrective Actions
☐ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202288	WELL	PR	06/01/2024	GW	001-07693	ALBERT SACK D 3	PR

General Comment:
There have been no changes to equipment on location since previous inspection.

Date Run: 12/30/2024 Doc [#699506738]

Page 1 of 3

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:					
Corrective Action:				Date: _____	
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	202288	Type:	WELL	API Number:	001-07693	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	04/04/2024		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	5	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
ECMC Comments									
Comment				User			Date		
This inspection does not nullify any orders or corrective actions from the ECMC At time of inspection weather conditions were cold, slight wind, some clouds.				medinaj		12/20/2024			
Attached Documents									
You can go to ECMC Images (https://ecmc.state.co.us/weblink/) and search by document number:									
Document Num	Description	URL							
699506739	inspection pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6856561							