

# Inspection Photos

API: 061-06876

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 11/20/2024

County: KIOWA



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 3.** Drone aerial photo facing east along the former access road.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos



**Photo 2.** Drone aerial photo facing east along the former access road. Areas of the access road have not established perennial vegetation and will need to be reseeded.




**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:061-06876 | Date: 11/20/2024

## Inspection Photos



**Photo 3.** Drone aerial photo facing southeast along the former access road.



## Inspection Photos



**Photo 4.** Drone aerial photo facing east overlooking the location..



## Inspection Photos



**Photo 5.** Facing down toward the location. Areas of the location have not established perennial vegetation and will need to be reseeded.




**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:061-06876 | Date: 11/20/2024

## Inspection Photos



**Photo 6.** Drone aerial photo facing south overlooking the location. The location remains fenced for final reclamation.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:061-06876 | Date: 11/20/2024

## Inspection Photos



**Photo 7.** View of fence line which has undesirable tumble weeds caught in the fence.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:061-06876 | Date: 11/20/2024

## Inspection Photos



**Photo 8.** View of the surrounding reference area pasture with uniform native vegetation.

