

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/19/2024

Submitted Date:

12/30/2024

Document Number:

717000220

FIELD INSPECTION FORM

Loc ID 319939 Inspector Name: Finkenbinder, Chane On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Supervisor, ECME		jason.gomez@state.co.us	
,		cogcc@kpk.com	All Inspections
,		randy.silver@state.co.us	
,		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201948	WELL	PR	05/01/2024	GW	001-07352	UPRR 23 PAN AM D 2	SI

General Comment:

[Follow-up inspection / No change in equipment](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type: TRASH

Comment:

Corrective Action:

Date: 01/10/2025

Overall Good:

Spills:

Type	Area	Volume

In Containment:

Comment:

Multiple Spills and Releases?

Venting:

Yes/No:

Comment:

Corrective Action:

Date:

Flaring:

Type:

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 201948 Type: WELL API Number: 001-07352 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/10/2024 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Appeared to be plumbed to the surface

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary On Thursday December 19th, 2024 at approximately (11:36am) I, Inspector Chane Finkenbinder, conducted an on-site follow-up inspection. This is a follow-up inspection from Doc# 700902028 – Trash pile still on location and appears there is more trash added to the original pile. Operator: KP KAUFFMAN COMPANY INC Location name: UPRR 23 PAN AM D #2 API # 05-001-07352 Location ID #: 319939 County: Adams While there, I observed a shut in well. During this inspection the following possible compliance issues were observed: Rule 606: Trash & debris on location (east of ECDs & west of pump jack). Within the designated setback, remove trash & debris per Rule 606. Corrective action date 1/10/2025, See all attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection report.</p>	finkenbc	12/30/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717000221	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857282