

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/20/2024

Submitted Date:

12/30/2024

Document Number:

708700077**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
, SIMCOE		sjninspections@ikavenergy.co	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488909	SPILL OR RELEASE	AC	12/30/2024		-	State CF1 - Dry Creek	EI

General Comment:

This is an environmental inspection to document status of spill. See attached photos.

Spill reported to area Environmental Protection Specialist Jason Kosola via phone call on 12/20/2024. Spill of produced water from pipeline appears to be a long term, ongoing release into Dry Creek which is considered Waters of the State.

Inspected Facilities									
Facility ID:	488909	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER

Estimated Spill Volume:

Comment:

Spill of produced water from pipeline was reported via phone call on 12/20/2024. Spill appears to be a long term release occurring since at least 9/17/2024 as shown on the attached aerial photos. Multiple domestic water wells are present downstream from where release entered Dry Creek.

Corrective Action:

Operator shall send spill notification to owners of domestic water wells that meet the following criteria: a screened interval less than or equal to 80 feet below ground surface, wellbore located within 200 feet of the banks of Dry Creek, and wellbore located within 1 mile downstream from where spill entered Dry Creek.

Date: 01/20/2025

Reportable: YES

GPS: Lat 37.214951

Long -107.649598

Proximity to Surface Water: 0

Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num:

Owner Name:

GPS :

Lat

Long

Field Parameters:

Sample Location:

Comment:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708700078	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857549
708700079	Google earth image	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857550
708700080	Google earth image map	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857551

Date Run: 12/30/2024 Doc [#708700077]

Page 3 of 3