

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/23/2024

Submitted Date:

12/30/2024

Document Number:

717000234

FIELD INSPECTION FORM

Loc ID 320062 Inspector Name: Finkenbinder, Chane On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
,		randy.silver@state.co.us	
, COGCC		conor.pesicka@state.co.us	
Supervisor, ECME		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202467	WELL	PR	05/01/2024	GW	001-07872	UPRR 23 PAN AM M 3	SI

General Comment:

[Follow-up inspection DOC# 71700078 / No equipment has been changed](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment: Weeds throughout location

Corrective Action:

Rule 606: Weeds, dead weeds, trash, debris & unnecessary / unused equipment. Within the designated setback (25 feet around any and all equipment), remove trash, debris and weeds per Rule 606. Corrective Action Date 1/10/2025 . See attached all photos

Date: 01/10/2025

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Horizontal Heated Separator

1

Comment:

Flow lines for the separator are not LOTO/and are unmarked.

Corrective Action:

• Rule 1102.g.: Flowline risers not LO/TO or marked are considered unused equipment. Comply with Rule 1102.g. For unused, unmarked flow line risers 24 hrs. To lock out tag out. 30 days to remove riser. Corrective Action Date 1/31/2025. See attached photo # 5, 6 & 7.

Date: 01/31/2025

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 202467 Type: WELL API Number: 001-07872 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 05/09/2024 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary On Monday December 13:45pm 23rd at approximately (). I, Inspector Chane Finkenbinder, conducted an on-site follow-up inspection. This is a follow up inspection from DOC# 717000078. No actions were taken to correct the corrective actions from DOC# 717000078. Operator: KP KAUFMANN Location name: UPRR 23 PAN AM M3 API # 001-07872 Location ID #: 320062 County: Adams While there, I observed a shut in well. During this inspection the following possible compliance issues were observed: Rule 606: Weeds, dead weeds, trash, debris & unnecessary / unused equipment. Within the designated setback (25 feet around any and all equipment), remove trash, debris and weeds per Rule 606. Corrective Action Date. See attached all photos 1/10/2025 Rule 1102.g.: Flowline risers not LO/TO or marked are considered unused equipment. Comply with Rule 1102.g. For unused, unmarked flow line risers 24 hrs. To lock out tag out. 30 days to remove riser. Corrective Action Date 30 days. See attached photo # 4,5 & 6</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection report.</p>	finkenbc	12/30/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717000235	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857602