

WELL NAME: LYNCH 43-30, API #: 071-08170, INSP. # 716300371



PHOTO 1: WELL SIGN



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



PHOTO 2: LOCATION.





PHOTO 3: ORIG. WELLHEAD AND EQUIPMENT.





PHOTO 4: TR WELLHEAD AND EQUIPMENT.



PHOTO 5: AREA OF IMPACTED SOIL UNDER LEAKING DRIVE MOTOR. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. CA DATE 1-9-25





PHOTO 6: DRIVEHEAD MOTOR LEAKING HYDRAULIC OIL. REPAIR EQUIPMENT PER RULE 606. CA DATE 1/9/25.