

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/30/2024

Submitted Date:

12/30/2024

Document Number:

715201410

**FIELD INSPECTION FORM**

Loc ID 321738 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 17180  
Name of Operator: CITATION OIL & GAS CORP  
Address: 14077 CUTTEN RD  
City: HOUSTON State: TX Zip: 77069

**Findings:**

- 15 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207883	WELL	PR	02/01/2024	OW	017-06818	ARAPAHOE UNIT 170(14-9)	PR

**General Comment:**

SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through farm ground		
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Sticker on chemical drum		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Lease sign at tank battery		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks. Missing labels on east oil tanks and water tank		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 01/30/2025
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:			Date:

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	2-Gas meter runs on north side of treaters		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Lufkin 228		
Corrective Action:			Date:
Type: Vertical Separator	# 1		

Comment:	Vertical gas separator in north treater shed	Date:	
Corrective Action:		Date:	
Type:	Ancillary equipment # 5		
Comment:	Electric panel, telemetry equipment, cathodic rectifier, chemical drum in metal shed, gas circ pump at battery	Date:	
Corrective Action:		Date:	
Type:	Vertical Heater Treater # 2		
Comment:	2-100 bbl treaters with metal sheds	Date:	
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		38.843680,-102.127640
Comment:	Water tank is on north side of production tanks				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared berms with oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLs	STEEL AST		38.843680,-102.127640
Comment:	Central tank battery for Arapahoe Unit (170, 171, 172, 173)				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**AirsID**

API Number	AirsID
------------	--------

**Wells Served By Facilities Above**

API Number

017-06832

017-06886

017-06838

017-06818

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 207883 Type: WELL API Number: 017-06818 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Central tank battery for Arapahoe Unit \(170, 171, 172, 173\) 630' W @ 38.843680/-102.127640](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715201418	pumping unit	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857788">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857788</a>
715201419	tank battery	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857789">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857789</a>